Austin T Owen

From: Austin Carter <acarter@ttb.com>
Sent: Monday, October 5, 2026 9:29 AM
To: Sisung, Matthew; Jason Scott; Nate Wallace; Chuck Rogall
Cc: Trefil, Dalton; Austin T Owen
Subject: RE: DNOW PO# 663013318 Status Update (TTB Order 26H109710)

##CAUTION##: This email originated from outside of CMS/CE.
Remember your security awareness training: Stop, think, and use caution before clicking links/attachments.

Matthew,

Good morning.

It would appear that the bend ID's for these two bends got swapped at coater prior the final stencil application.
I can confirm based on our records, that all 30° bends on this order were from B416745 and all the 45° bends on this order were from B416740.

TTB authorizes field to correct the bend tagging accordingly.

We will also notify our coating facility and initiate a corrective action for this occurrence.

Please let us know if we can provide anything further toward resolution of this issue.

Regards,

Austin Carter
Project Director
_____

Tulsa Tube Bending
918-446-4461 Main | 918-508-7226 Direct|385-204-7179 Mobile
acarter@ttb.com | www.ttb.com [ttb.com]

"Serving others. Building people. Pursuing excellence."
67 years of excellence

From: Sisung, Matthew <Matthew.Sisung@dnow.com>
Sent: Sunday, October 4, 2026 6:56 PM
To: Austin Carter <acarter@ttb.com>; Jason Scott <JScott@ttb.com>; Nate Wallace <nwallace@ttb.com>; Chuck Rogall <crogall@ttb.com>
Cc: Trefil, Dalton <Dalton.Trefil@dnow.com>; Austin T Owen <austin.owen@cmsenergy.com>
Subject: RE: DNOW PO# 663013318 Status Update (TTB Order 26H109710)

Austin Carter and Jason, please see attached and below. This needs resolved as it has halted work.

Matt,

See the below issue found in the field today. This is urgent. Production has been halted on these fittings until we find out why the stamping is wrong and doesn't match the paperwork.

It was discovered in the field that two (2) 8in 0.322" WT X-52 Induction Bends have incorrect stamping relative to their actual bend angles. Examination of delivered paperwork suggests this error carries through to the MTR's for the pipe and the certificates of compliance. The joints observed are:

8" 0.322" WT X-52 Bend ID 109149-1-2 with a stamped heat number of B416745 (Stamped 30 degrees but is 45 degrees)

8" 0.322" WT X-52 Bend ID 109149-2-1 with a stamped heat number of B416740 (Stamped 45 degrees but is 30 degrees).

All other delivered 30 degree and 45 degree bends reflect the following.
30 Degree Bend Heat Numbers are B416745
45 Degree Bend Heat Numbers are B416740

Attached are the bend packets for each for review, along with pictures of pipe stamping.

Currently, we are cutting the two bends out of fabricated assemblies until this issue can be resolved.

Please let me know if any additional information is needed,

Thank you,

Matt Sisung

Inside Sales Representative
Cell: 989-330-1511

Office: 989-773-9948
1701 Gover Parkway
Mt.Pleasant, MI 48858
matthew.sisung@dnow.com
Let us know how we are doing at CP1@dnow.com

Please note: DNOW stock items are returnable dependent on management approval and assuming material is in resalable condition. Returns for buyout purchases are subject to vendor/manufacturer approval and may be subject to restocking fees. Any item that is coated, modified, engineered, or automated; or in any other way customized to a specific application is non-returnable and non-cancellable unless arrangements are made prior to purchase authorization. All factory valves are non-returnable, non-cancellable.