LAB NOTE · NICLA VISION + GROVE WIO-E5

Why the new LoRa modules did not answer

1 · Symptom

New modules stayed silent

Same PCB, same code: old modules answered AT commands, brand-new ones gave no reply at all.

2 · Cause

A baud rate mismatch

New Wio-E5s ship at 9600 baud. The Nicla's TX/RX UART cannot run that slow in our setup, so it never reached them.

3 · Fix

One-time setup per module

An OpenMV script talks to the module at 9600 and switches it to 19200. The setting is saved, so it then works like the old ones.

Old modules	already set to 19200 baud	**Worked**
New modules	factory default 9600 baud → AT+UART=BR,19200	**Fixed**