

Our Ref : 16880
Your Ref : 28982 AR AB

Date of Report : 17 December 2025
Date Instructed : 16 December 2025

Date of Inspection : 17 December 2025
Date of Accident : 13 December 2025

Instructed By : NATIONWIDE ASSIST LTD
Address : 25 - 39, SMALLHEATH HIGHWAY, BIRMINGHAM, B10 0EU

Insured : MR. S RAMZAN
Third Party :
Address :

VEHICLE DETAILS

Reg No : BD23AUV
Make : TOYOTA
Model : COROLLA
Body : HATCHBACK
Spec : VVTI, ICON
Engine CC : 1798
Fuel Type : HYBRID
Chassis No : SB1Z93BE70E345931
Mileage : 65000 Miles
Date of Reg : 31 March 2023
Tax Expiry : // // // // //
Doors : 5
Transmission : AUTOMATIC
Colour : BLACK
Audio : AUDIO
Extras : NON APPARENT
Paint : CLEAR OVER BASE

TYRE TREADS (mm)

OSF :
NSF :
OSR :
NSR :
Others :

STATIC CHECKS

Steering : SATISFACTORY
Footbrake : SATISFACTORY
Handbrake : SATISFACTORY
Seatbelts : SATISFACTORY


IMPACT DETAILS

Mechanical :
Body : HEAVY

Inspection Location : RECOVERY AGENT

Vehicle Status : TOTAL LOSS
UNROADWORTHY

Pre-Accident Condition of Vehicle : GOOD
Cause of Damage : ACCIDENT



Repairer : CAMS RECOVERY, SMALL HEATH HIGHWAY, SMALL HEATH, BIRMINGHAM
Labour Rate £ 90.00
Repair Time In Days : 0

Labour	£	2340.00	V.A.T @ 20 %	£	2126.54
Paint / Materials	£	1348.00	Provisional Reserve	£	12759.24
Parts	£	6780.70	Excess	£	
Specialist	£	164.00	Vehicle Market Value	£	14500.00
Total Exc VAT	£	10632.70			
Total Inc VAT	£	12759.24			

Glass's Retail Value	£	14700.00	Glass's Trade Value	£	12050.00	Average Mileage Of	:	65000
Glass's Older Cars Value	£		Dealer Retail Value	£		Glass's Private Sale Value	£	

Engineers Valuation Figure	£	14500.00	Salvage Value	£	2000.00
(Adjustments regarding vehicle age, mileage, date of registration included)			Motor Salvage Category	:	S

Recovery Charges £ 350.00
Date Storage Commenced :

Charges Being Incurred : Storage Per Day £ 35.00

Comments / Repair Notes :
THE ABOVE VEHICLE HAS SUSTAINED HEAVY FRONTAL IMPACT DAMAGE, BIASED TOWARDS THE NEAR SIDE, IN A FRONT TO REAR MOTION,
NO ESTIMATES WERE RAISED, IN THE ABSENCE OF ESTIMATES, THIS REPORT CONTAINS PROJECTED COSTS BASED UPON THE IMAGES OF THE DAMAGE SUSTAINED IN THE INCIDENT AND SUBJECT TO GLASSMATIC TIMES AND SCHEDULES, PLEASE DEAL WITH ACCORDINGLY. VALUATION BASED UPON ADVISED MILEAGE. VEHICLE CHECKS MAY REVEAL ADDITIONAL DAMAGE AND INCREASE COSTS ...PROJECTED REPAIR COSTS BASED UPON 26 HRS @ £90 PER HOUR

ENGINEER: STEVE PRINT A.M.I.M.I. AQP IA01047

A handwritten signature in black ink that reads "Steve Print".

I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

PART REQUIREMENTS

Our Ref : 16880
Your Ref : 28982 AR AB

Parts Specification	Action
FRONT BUMPER	Replace With New
FRONT BUMPER BRACKETS	Replace With New
FRONT BUMPER SUPPORT BAR	Replace With New
FRONT BUMPER PADS	Replace With New
FRONT BUMPER MOULDINGS	Replace With New
FRONT PANEL	Replace With New
CROSS MEMBER	Replace With New
FRONT SKIRT	Replace With New
FRONT GRILLE	Replace With New
FRONT LOWER GRILLE	Replace With New
BONNET	Replace With New
BONNET HINGES	Replace With New
BONNET LOCK AND CATCH	Replace With New
RADIATOR FAN COWLS	Replace With New
OFF/SIDE FRONT HEADLAMP	Replace With New
OFF/SIDE FRONT HEADLAMP BEZEL	Replace With New
OFF/SIDE FRONT HEADLAMP SUPPORT PANEL	Replace With New
OFF/SIDE FRONT FOG LIGHT	Replace With New
OFF/SIDE FRONT WING AND MOULDING	Replace With New
OFF/SIDE FRONT WING LINER	Replace With New
OFF/SIDE FRONT INNER WING	Repair
OFF/SIDE FRONT CHASSIS	Repair
OFF/SIDE DOOR MIRRORS	Repair
OFF/SIDE FRONT DOOR SKIN	Repair
OFF/SIDE FRONT DOOR MOULDINGS	Replace With New
WASHER BOTTLE	Replace With New
OFF/SIDE FRONT WHEEL HUB	Check
OFF/SIDE FRONT SUSPENSION HUB	Check
OFF/SIDE FRONT WHEEL BEARING	Check
OFF/SIDE FRONT SUSPENSION UPPER ARM	Check
OFF/SIDE FRONT SUSPENSION LOWER ARM	Check
MOULDINGS	Replace With New
VARIOUS MINOR ITEMS	Replace With New
PAINT AND PROCESS MATERIALS	Replace With New
BLEND IN SURROUNDING PANELS	Repair
JIG VEHICLE AND MONITOR ALIGNMENT	Repair
INITIAL PULL AND CLAMP	Repair
~~~~~ SPECIALIST ~~~~~	Specialist
CAR CARE KIT	Specialist
GEOMETRY	Specialist
JOB ALLOWANCE	Specialist
VALET	Specialist
EPA CHARGE	Specialist
ADAS CALIBRATION	Specialist

I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not.  
Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

**Instructed by :**

NATIONWIDE ASSIST LTD  
25 - 39, SMALLHEATH HIGHWAY, BIRMINGHAM, B10 0EU

## INVOICE / FEE NOTE

**Our Ref** : 16880  
**Your Ref** : 28982 AR AB  
  
**Date of Inspection** : 17 December 2025  
**Date of Report** : 17 December 2025  
  
**Vehicle** : TOYOTA COROLLA VVTi, ICON  
**Reg No** : BD23AUV  
**Date of Reg** : 31 March 2023

**Client** : MR. S RAMZAN

**Engineers Report Fee :** £ 85.00

**Any additional charge details :**

**TOTAL** £ 85.00