

N086AV (S/N: W15071882022) — Serial Console Access Diagnostic Report

Immfly Ground Operations / IT — Session: August 21, 2026

Field	Value
Machine	N086AV (S/N: W15071882022)
Affected component	Serial console access (no OS or BIOS output observed)
Initial symptom	No console output of any kind via serial connection after powering on the unit
Diagnostics possible	None — no console access means no OS-level or BIOS-level commands could be run
Root cause	Not determined — could not be isolated without console access
Recommended action	Physical inspection required; verify cable/adapter/ baud rate against a known-good unit before

Narrative Summary

N086AV was connected via its serial console port and powered on for routine diagnostics. At no point did the serial terminal (minicom) display any output — no BIOS/POST messages, no bootloader output, and no operating system boot text of any kind, despite the unit being powered on. This is a more fundamental symptom than the cases previously documented for other units in the fleet, which typically involved a specific subsystem failure (modem, disk, or display) while the machine itself remained reachable via console or SSH.

Because P100 units in this fleet have no video output and are administered exclusively through the serial console (via minicom) or, once booted, via SSH over the VPN, a complete absence of serial output at power-on effectively blocks all further diagnosis. Unlike prior cases (e.g. N158AV, where a live USB rescue environment could be booted to inspect the disk), no commands could be issued and no logs could be collected for N086AV, since there is no confirmed console access to begin with.

No physical inspection of the unit (motherboard, serial header, power delivery) was possible remotely. This report documents the observed symptom and recommends a structured set of physical checks to isolate whether the fault lies in the console/cabling path or in the machine itself before further remote diagnostics can resume.

Checks Attempted

1. Physical connection

Serial console cable connected from the administration laptop/adapter to N086AV's serial port.

2. Power-on

Unit powered on with the serial terminal (minicom) already open and listening.

3. Console monitoring

No output of any kind observed in minicom at any point after power-on — no BIOS/POST text, no boot messages, no login prompt. The terminal remained completely blank.

Recommended Next Steps

Since no console output was captured, the fault could not be isolated to a specific layer (cabling, adapter/ baud-rate mismatch, BIOS/POST failure, or a dead board) from this session alone. The following checks are recommended, roughly in order of ease, before treating this as a confirmed hardware failure of N086AV itself:

- 1. Rule out the cable/adapter/settings first.** Connect the same serial cable and USB-to-serial adapter to a known-healthy P100 (e.g. N098AV) and confirm console output appears normally. This isolates whether the problem is on the cabling/adapter side rather than N086AV itself. Also double-check minicom's port settings (correct `/dev/ttyUSBx` device, 115200 8N1, no hardware/software flow control) — a mismatched device or baud rate produces exactly this symptom of a silently blank terminal.
- 2. Confirm the unit is actually powering on.** Check for any physical signs of life on N086AV itself — power LED, fan spin-up, or NIC link lights — to distinguish between "the machine is not powering on at all" (a power delivery problem) versus "the machine powers on but produces no serial output" (a POST/BIOS or serial-header problem).
- 3. If the cable/adapter test on a known-good unit works fine and N086AV shows signs of power** but still produces no console output, the fault likely sits at the board level (failed serial header, POST failure preventing any output, or a dead/unresponsive motherboard) and the unit should be escalated for physical inspection and bench-level diagnostics, following the same repair-order workflow used for other confirmed hardware failures in the fleet (N120AV, N158AV, N096AV, N010AV).