



N051AV (S/N: W20051875722) — No-Boot / BIOS Inaccessible Diagnostic Report

Immfly Ground Operations / IT — Session: August 27, 2026

Field	Value
Machine	N051AV (S/N: W20051875722)
Affected component	Boot/POST sequence — unit cannot be interrupted to enter BIOS setup
Initial symptom	BIOS setup menu is not reachable, blocking the planned disk re-imaging procedure
Diagnostics possible	Very limited — without BIOS/console access, no boot device order change or OS-level diagnostics could be performed
Root cause	Not determined — could not be isolated without console/BIOS access
Recommended action	Physical inspection required; verify serial console cable/adaptor against a known-good unit before assuming a motherboard/POST-level fault

Narrative Summary

N051AV was scheduled for disk re-imaging as part of the fleet's ongoing golden-image rollout. The first required step for this procedure is entering the BIOS setup menu to change the boot device priority so the unit boots from external media (USB/external disk) instead of its internal disk. Despite repeated attempts, the BIOS setup menu could not be reached on N051AV — the unit does not respond to the interrupt sequence normally used to enter setup during POST.

As with other units in this fleet, P100 hardware has no video output of its own and is administered exclusively via serial console, so BIOS/POST access depends entirely on that console path working correctly. Without the ability to reach BIOS, the planned re-imaging procedure for N051AV could not proceed, and no further OS-level or BIOS-level diagnostics could be collected remotely — this is the same fundamental blocker previously documented on N086AV and N018AV, where a complete absence of usable boot-stage interaction prevents any further software-level troubleshooting.

No physical inspection of the unit (motherboard, serial header, power delivery) was possible as part of this session.

Checks Performed

1. BIOS entry attempts

Repeated attempts to interrupt the boot sequence and reach BIOS setup (required to change boot device order ahead of the planned re-image) were unsuccessful — the setup menu could not be entered.

Recommended Next Steps

Since BIOS/console access could not be established, the fault could not be isolated to a specific layer (cabling, serial adapter/baud-rate mismatch, a BIOS-level configuration issue such as a disabled setup prompt, or a deeper POST/board-level fault) from this session alone. The following checks are recommended, in order of ease, before treating this as a confirmed hardware failure of N051AV itself — following the same protocol used for the similar cases previously documented on N086AV and N018AV:

- 1. Rule out the cable/adaptor/settings first.** Connect the same serial cable and USB-to-serial adapter used with N051AV to a known-healthy P100 and confirm console output and BIOS entry work normally there. This isolates whether the problem is on the cabling/adaptor side rather than N051AV itself. Also double-check the terminal's port settings (correct device, 115200 8N1, no hardware/software flow control) and confirm the interrupt key/timing being used matches this fleet's BIOS (Setup Prompt Timeout, as seen on other units, is typically only a few seconds).
- 2. Confirm whether any boot-stage output is visible at all.** If the console shows the BIOS splash/POST text but simply does not respond to the setup interrupt key, this points to a keyboard-input or console-configuration issue rather than a boot failure. If the console shows nothing whatsoever (a fully blank terminal from power-on), this is consistent with the more severe no-console-output cases (N086AV, N018AV) and points toward a POST-level or board-level fault.
- 3. If the cable/adaptor test on a known-good unit works fine** and N051AV still cannot be interrupted into BIOS setup, the fault likely sits at the board/firmware level and the unit should be escalated for physical inspection and bench-level diagnostics, following the same repair-order workflow used for other confirmed hardware failures in the fleet.