PROPERTY HEALTH CHECK UK®

Home MOT

Property Condition Inspection Report

Protecting Homes Before Problems Become Claims.

SURVEY LEVEL

Gold — External + internal

Domestic property

Property	12 Acacia Avenue, Headingley, Leeds, LS6 2AB
Policyholder	Jane Smith 07700 900123 jane.smith@example.com
Claim number	CLM-48213
Policy number	HP-99812-07
Instructing client	Northern Mutual Home Insurance
Inspection date	5 October 2026
Inspector	Alex Morgan
Report reference	HM-2610-0002

No photograph

OVERALL HOME MOT RATING

Poor

11 × 2 — Urgent

7 × 3 — Planned

1 × 4 — Routine

1 Property & policyholder details

Policyholder	Jane Smith	**Inspection date**	5 October 2026
Property address	12 Acacia Avenue, Headingley, Leeds	**Postcode**	LS6 2AB
Property type	Semi-detached	**Approx. age**	1919–1944
Construction	Cavity brick / block	**No. storeys**	2
Roof	Hipped, Natural slate	**No. bedrooms**	3
Weather at inspection	Dry	**Occupancy**	Occupied
Inspector	Alex Morgan	**Overall condition**	Poor

Property description

> *The subject property is a two-storey semi-detached house, believed to date from the inter-war period, of cavity masonry construction beneath a hipped roof covered in natural slate. External walls are rendered and the property has uPVC double-glazed windows. The accommodation includes three bedrooms. At the time of inspection the property was occupied and the weather was dry.*

2 Roof survey (drone)

Question	Answer	Report wording
Overall condition of the roof coverings	Fair	The roof coverings appeared serviceable but showed signs of age, wear or minor deterioration. Further checking would be required to establish the extent of preventative maintenance needed to reduce the likelihood of future damage. Roof coverings and associated weathering details need to be capable of resisting normal weather exposure. Defective coverings, failed mortar, damaged flashings, blocked drainage or deteriorated junctions can increase the risk of water ingress during severe

		weather.
Approximate height to the ridge	8.4 m	The approximate height to the ridge was estimated at 8.4 m.
Is the building over 11 metres in height?	No	The building was assessed as being under 11 metres in height.
Is it a Higher-Risk Building (18 m+ or 7+ storeys with 2+ residential units)?	No	The building does not appear to meet the definition of a Higher-Risk Building under the Building Safety Act 2022.
Are there slipped, cracked, missing or displaced slates or tiles?	Yes	Slipped, cracked, missing or displaced roof coverings were noted. These may allow water ingress during periods of wind-driven rain and would require further investigation, further checking and potentially repairs.
Is there visible evidence of recent storm damage to the roof?	No	No visible evidence of recent storm damage to the roof was noted.
Are ridge, hip, verge and flashing details secure and intact?	No	Defects were noted to the ridge, hip, verge and/or flashing details. Failed mortar or lifted flashings are a common point of water entry during severe weather and would require further investigation, further checking and potentially repairs.

3 External / storm-readiness inspection

Element	Condition	Description / evidence
Roof drainage / gutters	Fair	The rainwater goods appeared serviceable but showed signs of age, wear or minor deterioration. Further checking would be required to establish the extent of preventative maintenance needed to reduce the likelihood of future damage. Rainwater goods need to be kept clear, securely fixed and capable of discharging water effectively. Defects or blockages may increase the risk of water overflowing against the building fabric. Gutters were noted to be holding debris and/or

		vegetation, which may cause water to overflow against the building fabric. No leaking or disconnected sections were visible. Staining to the wall surfaces below the gutter line indicates that overflowing has occurred. Downpipes were observed to discharge into gullies or drainage points.
Fascia / soffits	Good	The fascias and soffits appeared to be in generally good condition at the time of inspection, with no significant visible defects noted within the limitations of a visual inspection. Fascias and soffits are of non-timber (e.g. uPVC) construction. Boards appeared secure. No evidence of bird or pest entry was noted.
Verge / ridge details	Poor	The verge and ridge details showed visible deterioration and/or defects that may reduce its ability to perform effectively during adverse weather and would require further investigation, further checking and potentially repairs. Cracked or missing bedding mortar was noted to the ridge and/or hip tiles and would require further investigation, further checking and potentially repairs. No loose ridge or hip tiles were noted. Defects were noted to the verge pointing or dry-verge system and would require further investigation, further checking and potentially repairs.
Chimney stack / flashings	Poor	The chimney stack and flashings showed visible deterioration and/or defects that may reduce its ability to perform effectively during adverse weather and would require further investigation, further checking and potentially repairs. The stack appeared upright. Eroded or missing pointing was noted to the chimney stack and would require further investigation, further checking and potentially repairs. The chimney flashings appeared lifted, cracked or defective, which is a common route for water ingress, and would require further investigation, further checking and potentially repairs. Pots and cowls appeared secure. Further comments: Flashing to rear of stack lifted by approx. 20 mm.
External walls	Fair	The external walls appeared serviceable but showed signs of age, wear or minor deterioration. Further checking would be required to establish the extent of preventative maintenance needed to reduce the likelihood of future damage. External walls and associated joints need to remain weather-resistant.

		Open joints, cracking, failed pointing or defective interfaces may allow water penetration during periods of wind-driven rain. No significant cracking was noted to the external walls. Pointing appeared generally serviceable. Cracked, hollow-sounding or debonded render was noted. Defective render can allow water to become trapped behind it and would require further investigation, further checking and potentially repairs. No significant spalling was noted. The damp-proof course was visible and generally 150 mm or more above external ground level.
Windows / seals	Good	The windows and seals appeared to be in generally good condition at the time of inspection, with no significant visible defects noted within the limitations of a visual inspection. Misting between panes was noted to one or more double-glazed units, indicating failed hermetic seals. No cracked or broken panes were noted. Frames appeared sound. Perimeter sealant appeared intact.
External doors	Good	The external doors appeared to be in generally good condition at the time of inspection, with no significant visible defects noted within the limitations of a visual inspection. Doors, frames and thresholds appeared sound. Weather seals appeared effective. External doors appeared secure with locks fitted.
Drainage, gullies & French drains	Fair	The below-ground drainage and gullies appeared serviceable but showed signs of age, wear or minor deterioration. Further checking would be required to establish the extent of preventative maintenance needed to reduce the likelihood of future damage. Gullies appeared clear and free-running where visible. Inspection chamber covers appeared intact. A French drain / perimeter drainage system is present around the property. The perimeter drainage appeared silted, obstructed or overgrown, which may reduce its effectiveness during heavy rainfall, and would require further investigation, further checking and potentially repairs. No ponding was noted adjacent to the building.
Boundary walls & fences	Fair	The boundary walls, fences and gates appeared serviceable but showed signs of age, wear or minor deterioration. Further checking would be required to establish the extent of preventative maintenance needed to reduce the likelihood of future damage.

		Boundary walls appeared stable. Fence panels, posts or gates were damaged, loose or decayed and are vulnerable to wind damage. There are no retaining walls.
Trees & grounds	Not recorded	Large trees were noted within falling distance of the building. These present a risk of damage during storm conditions and their condition would require further checking. No trees were noted close enough to influence the foundations. Paths and drives appeared serviceable.
Outbuildings / structures	Fair	See the outbuildings schedule (1 structure).

4 Internal rooms — measurements & condition

Length × Width × Height recorded in metres. Floor area calculated as Length × Width. Each room was visually inspected and its condition recorded against the selected assessment. Any identified defects are listed within the further investigation schedule of this Home MOT report together with their priority.

Room / area	Level	L (m)	W (m)	H (m)	Area (m²)	Condition	Defects	Photo ref.
Living room	Ground floor	4.6	3.8	2.6	17.48	Good	1	
Kitchen	Ground floor	3.9	2.8	2.5	10.92	Good		
Bedroom 1	First floor	4.1	3.5	2.5	14.35	Fair		

Living room · Ground floor · 17.48 m² Good

The ceiling is flat and plastered with decorative coving and a central ceiling rose. Walls have a smooth plaster skim finish with painted decoration. The floor is laid with solid wood flooring. A chimney breast with fireplace is located on the party wall.

The ceiling comprises a smooth plastered finish, a ceiling rose and coving. Walls are finished with a smooth plaster skim. The floor is finished with solid wood flooring. Notable features include a chimney breast, a fireplace, a radiator and a bay window. The room was found to be in good condition, with no significant defects noted within the limitations of a visual inspection. No evidence of dampness or water staining was noted. No significant cracking was noted. Physical damage to the finishes was noted which would potentially require patch repair. Ventilation appeared adequate.

- moderate Hole to plaster at low level to the left of the door; would require further investigation and potentially repair. (Left-hand wall beside the door)

Kitchen · Ground floor · 10.92 m² Good

The ceiling comprises a smooth plastered finish. Walls are finished with a smooth plaster skim and ceramic tiling. The floor is finished with ceramic or stone tiling. Notable features include fitted kitchen units and a radiator. The room was found to be in good condition, with no significant defects noted within the limitations of a visual inspection. No evidence of dampness or water staining was noted. No significant cracking was noted. No physical damage to finishes was noted. Ventilation appeared adequate.

Bedroom 1 · First floor · 14.35 m² Fair

The ceiling comprises a textured (Artex-type) coating. Textured coatings of this type applied before 2000 may contain asbestos; further checking would be required before any disturbance. Walls are finished with wallpaper or lining paper. The floor is finished with fitted carpet. Notable features include a chimney breast, built-in storage and a radiator. The room was found to be in fair condition, with signs of wear and minor deterioration to finishes. Evidence of dampness, water staining and/or mould growth was noted. The cause could not be determined from a visual inspection and would require further investigation, further checking and potentially repairs. Cracking was noted to wall and/or ceiling surfaces. Further checking would be required to establish whether this is of structural significance or is typical shrinkage cracking. No physical damage to finishes was noted. Ventilation appeared adequate.

5 Roof space, services & damp

Services were inspected visually only and were not tested.

Element	Summary	Description / evidence
Roof space / loft	Defects noted	The roof space was accessed and inspected from the hatch / boarded areas. Evidence of water ingress and/or staining was noted within the roof space and would require further investigation, further checking and potentially repairs. Roof timbers appeared sound where visible. Insulation is present within the roof space. There is no underlay, which is typical of a roof of this age.
Services & safety (visual)	Satisfactory	Smoke alarms were noted on each floor. A carbon monoxide alarm was noted near fuel-burning appliances. The consumer unit appeared to be of a modern type incorporating RCD protection. No visible leaks were noted from exposed pipework.
Damp, condensation &	Satisfactory	No evidence of rising or penetrating damp was noted. No significant condensation or mould

movement		growth was noted. No timber decay or insect activity was noted where visible. No evidence of significant structural movement was noted internally.

6 Garage / summerhouse / outbuildings

Structure	L	W	H	Area m²	Roof	Walls	Condition	Description / defects
Detached garage	5.5	2.9	2.4	15.95	Poor	Fair	Fair	Single garage of brick construction beneath a flat felt roof; ponding noted to the rear of the roof.

The structure was visually inspected for general condition, weather resistance and obvious defects. Maintenance requirements would need to be addressed to reduce vulnerability to wind and rain.

7 Defects, maintenance & storm vulnerability

Assessment	Selection	Wording / inspector comments
Maintenance standard	Poorly maintained	The property appeared to be poorly maintained. A number of items would require further investigation, further checking and potentially repairs.
Storm vulnerability	Not recorded	
Pre-existing defects observed	Not recorded	
Evidence of previous repair	Not recorded	
Water ingress indicators	Not recorded	
Overall priority	Not recorded	

8 Further investigation schedule (policyholder action plan)

The following matters were identified during the inspection. Each would require further

investigation, further checking and potentially repairs. Priorities indicate the suggested order of attention; the final column is for the policyholder to record completion and evidence.

Priority	Area / defect	Further investigation required	Completed / evidence
2 — Urgent	**Roof survey (drone)**	Slipped, cracked or missing roof coverings — would require further investigation, further checking and potentially repairs.	
2 — Urgent	**Roof survey (drone)**	Defective ridge, hip, verge or flashing details — would require further investigation, further checking and potentially repairs.	
2 — Urgent	**Verge / ridge details**	Cracked or missing ridge/hip mortar — would require further investigation, further checking and potentially repairs.	
2 — Urgent	**Verge / ridge details**	Defective verge pointing/dry-verge — would require further investigation, further checking and potentially repairs.	
2 — Urgent	**Chimney stack / flashings**	Eroded chimney pointing — would require further investigation, further checking and potentially repairs.	
2 — Urgent	**Chimney stack / flashings**	Defective chimney flashings — would require further investigation, further checking and potentially repairs.	
2 — Urgent	**External walls**	Defective render — would require further investigation, further checking and potentially repairs.	
2 — Urgent	**Drainage, gullies & French drains**	French drain silted or obstructed — would require further investigation, further checking and potentially repairs.	
2 — Urgent	**Roof space / loft**	Water ingress within the roof space — would require further investigation, further checking and potentially repairs.	
2 — Urgent	**Detached**	Detached garage in fair condition —	

	garage	would require further investigation, further checking and potentially repairs. *Single garage of brick construction beneath a flat felt roof; ponding noted to the rear of the roof.*	
2 — Urgent	**Bedroom 1**	Damp, staining or mould — would require further investigation, further checking and potentially repairs.	
3 — Planned	**Roof drainage / gutters**	Gutters holding debris or vegetation — further checking and clearance would potentially be required.	
3 — Planned	**Roof drainage / gutters**	Staining indicating gutter overflow — further checking of gutter falls and capacity would be required.	
3 — Planned	**Boundary walls & fences**	Damaged or loose fences/gates — would require further investigation, further checking and potentially repairs.	
3 — Planned	**Trees & grounds**	Large trees within falling distance of the building — further checking of tree condition would be required.	
3 — Planned	**Living room**	Physical damage to finishes — patch repair would potentially be required.	
3 — Planned	**Living room**	Hole to plaster at low level to the left of the door; would require further investigation and potentially repair. (Left-hand wall beside the door)	
3 — Planned	**Bedroom 1**	Cracking to internal finishes — further checking would be required.	
4 — Routine	**Windows / seals**	Failed double-glazing seals (misting) — further checking would be required.	

9 Photo record

No photographs were taken.

10 Final summary & sign-off

Overall Home MOT rating	Poor
Key storm vulnerabilities	• Roof survey (drone): Slipped, cracked or missing roof coverings — would require further investigation, further checking and potentially repairs. • Roof survey (drone): Defective ridge, hip, verge or flashing details — would require further investigation, further checking and potentially repairs. • Verge / ridge details: Cracked or missing ridge/hip mortar — would require further investigation, further checking and potentially repairs. • Verge / ridge details: Defective verge pointing/dry-verge — would require further investigation, further checking and potentially repairs. • Chimney stack / flashings: Eroded chimney pointing — would require further investigation, further checking and potentially repairs. • Chimney stack / flashings: Defective chimney flashings — would require further investigation, further checking and potentially repairs. • External walls: Defective render — would require further investigation, further checking and potentially repairs. • Drainage, gullies & French drains: French drain silted or obstructed — would require further investigation, further checking and potentially repairs. • Roof space / loft: Water ingress within the roof space — would require further investigation, further checking and potentially repairs. • Detached garage: Detached garage in fair condition — would require further investigation, further checking and potentially repairs. • Roof drainage / gutters: Gutters holding debris or vegetation — further checking and clearance would potentially be required. • Roof drainage / gutters: Staining indicating gutter overflow — further checking of gutter falls and capacity would be required. • Boundary walls & fences: Damaged or loose fences/gates — would require further investigation, further checking and potentially repairs. • Trees & grounds: Large trees within falling distance of the building — further checking of tree condition would be

	required.
Priority matters	• Roof survey (drone) (priority 2): Slipped, cracked or missing roof coverings — would require further investigation, further checking and potentially repairs. • Roof survey (drone) (priority 2): Defective ridge, hip, verge or flashing details — would require further investigation, further checking and potentially repairs. • Verge / ridge details (priority 2): Cracked or missing ridge/hip mortar — would require further investigation, further checking and potentially repairs. • Verge / ridge details (priority 2): Defective verge pointing/dry-verge — would require further investigation, further checking and potentially repairs. • Chimney stack / flashings (priority 2): Eroded chimney pointing — would require further investigation, further checking and potentially repairs. • Chimney stack / flashings (priority 2): Defective chimney flashings — would require further investigation, further checking and potentially repairs. • External walls (priority 2): Defective render — would require further investigation, further checking and potentially repairs. • Drainage, gullies & French drains (priority 2): French drain silted or obstructed — would require further investigation, further checking and potentially repairs. • Roof space / loft (priority 2): Water ingress within the roof space — would require further investigation, further checking and potentially repairs. • Detached garage (priority 2): Detached garage in fair condition — would require further investigation, further checking and potentially repairs. • Bedroom 1 (priority 2): Damp, staining or mould — would require further investigation, further checking and potentially repairs.
Inspector summary	A Gold Home MOT inspection of 12 Acacia Avenue, Headingley, Leeds, LS6 2AB was carried out on 5 October 2026, comprising an inspection of the external fabric, roof, outbuildings and each internal room. The subject property is a two-storey semi-detached house, believed to date from the inter-war period, of cavity masonry construction beneath a hipped roof covered in natural slate. External walls are rendered and the property has uPVC double-glazed windows.

	The accommodation includes three bedrooms. At the time of inspection the property was occupied and the weather was dry. Overall, the property was assessed as being in poor condition. 19 matters were identified that would require further investigation, further checking and potentially repairs. These are set out in the further investigation schedule. There are requirements within the property that would need further investment, further checking and potentially repairs.

This Home MOT is a preventative property-condition inspection and is not a guarantee of insurance cover or future claim acceptance. Its purpose is to identify visible defects and maintenance issues so the policyholder can take reasonable preventative action.



Alex Morgan, MRICS
Property Health Check UK

DATE SIGNED
5 October 2026

Important: This inspection is a visual preventative assessment and does not constitute an insurance policy interpretation, guarantee of cover, structural survey, specialist survey, or guarantee that an insurer will accept a future claim. Property Health Check UK is not authorised by the Financial Conduct Authority and this report does not contain recommendations or advice; matters are recorded as requiring further investigation, further checking and potentially repairs.