Robot Procedure 2016_035

Dec 12th

2016

Preparation for Patch software loading and data collection procedure

[Patch Software loading to R30iB Controller]

Purpose:
Patch Software installation to overcome below troubles in R30iB:
Following problem occurs during Cartesian Soft Float due to Robot Software problem
A: Error excess alarm, that should occur if robot moves a certain amount of distance, becomes disabled.
B: Compensation excess alarm that occurs only in case of software bug occurs.

Condition of the failure to occur:

- Problem occurs during Cartesian Soft Float in case system corresponds to all of following conditions.

This document shows a procedure to install patch software into following version controller:

- Software Option: Soft Float (J612)
- Software Version: 7DC2/01-27 or 7DC3/01-21
- Robot Models: M-20iB/25, M-2000iA/1700L, M-2000iA/2300, M-710iC/20M, M-900iB/280L, R-2000iC/210L, R-2000iC/125L, R-2000iC/165R, R-2000iC/210F, R-2000iC/210R, R-2000iC/165F or M-410iC/500

Target Robots:
As listed in target list SR2016_194_(ROBOT)_Defect of Error excess alarm procedure during Cartesian SoftFloat on certain robot models.xls
Except for the case Soft Float Option is appended after shipment, 1096 robots has been shipped in total.

Tools Required:
Compact Flash Card – 2 Nos.
CF1 – Used for Collecting Image backup from each robot.
CF2 – With Patch Software data pre-loaded.
Note:
Please write CF1 & CF2 on respective compact flash cards for easy identification.

Preparation:
One time activity
Extract patch software content to compact flash card (CF2):
1. Unzip the mc.zip into memory card.
   Confirm that following files are extract to the root directory of the memory card.
   - a.cm
   - lg_p379.ls
   - svcode.bic

2. Collect Robot Image Backup for each Robot separately using Compact flash card (CF1):
   Please save image backup files before installation. (For safety)
   After collecting image backup, please save the content to your PC with Robot identification number (Old_XXXXXXXX)

<u>Procedure to Load Patch Software:</u>

a. Insert patch software memory card into memory card socket of controller.
b. Select file menu.
   - [MENUS]
   - FILE
c. Select MC: as memory device and show list of all files.
   - F5[UTIL]
   - 1 Set Device
   - Select "Mem Card (MC:)".
   - F2 [DIR]
   - Select "*.*" and press ENTER key
d. Select A.CM and press ENTER key.
e. Question • Execute A.CM? is displayed. Then press F4• YES

Caution after software update

1. In case “Patch(P379) is NOT necessary.” or “Version miss-match for P379.” is displayed, It’s NOT necessary to redo procedures.
2. Make sure that the FR:¥LG_P379.LS exists in the file screen.
3. Restart the controller (Turn OFF/ON the Power).
4. That's all for installation.
5. If any system alarm or system hangs during Power Off and On

   (Or)

   You want to restore state before patch installation, please restore image backup collected for this Robot from CF1 card.

END OF ACTIVITY