Aircraft Maintenance Work Order

Work order	WO-27-3381	**Aircraft registration**	ZK-MRQ
Aircraft type	AR-70 twin turboprop	**Serial number**	MSN 1418
Check type	A-check with defect rectification	**Station**	Port Ellery (PEY)
Opened	6 October 2027, 22:10 UTC	**Closed**	7 October 2027, 14:35 UTC

1. Defects reported by the crew

(i) PROBE HEAT 2 caution displayed during climb on sector PEY–KRW.

(ii) Pack 1 outlet temperature reached the upper limit during taxi at high ambient temperature.

(iii) Cabin crew reported that one emergency light near door 2L appeared dim during the preflight check.

2. Task cards

Task card	Description	ATA	Est. MH	Act. MH	Status
TC-0412-01	A-check zonal inspection, zones 100 to 600	05	14.0	15.5	Closed
TC-0412-02	Engine 1 and 2 oil filter change and chip detector inspection	79	3.0	2.5	Closed
TC-0412-03	Pitot probe 2 heater fault: troubleshoot and replace probe	34	4.0	5.0	Closed
TC-0412-04	Pack 1 outlet temperature high: clean heat exchanger	21	6.0	7.5	Closed
TC-0412-05	Main landing gear tyre pressure check and servicing	32	1.0	1.0	Closed
TC-0412-06	Cabin emergency lighting battery capacity test	33	2.0	2.0	Deferred
TC-0412-07	Lavatory smoke detector functional test	26	0.5	0.5	Closed
Total man-hours			**30.5**	**34.0**	

Task card TC-0412-06 was deferred under the minimum equipment list, category C, because a replacement battery pack was not in stock. The deferral expires on 17 October 2027.

All other task cards were completed and inspected, and no further defects were found during the zonal inspection.

3. Parts used

Part number	Description	Qty	Serial or batch number
SKP-34-1102	Pitot probe, heated	1	S/N 77104
SKP-79-0415	Oil filter element	2	Batch 27-0915
SKP-21-0338	O-ring, packing	4	Batch 26-1142
SKP-21-2200	Heat exchanger cleaning kit	1	Batch 27-0602

4. Fault message log

The following messages were downloaded from the central maintenance computer before and after the rectification work.

```
DATE     UTC   ATA    MSG   TEXT
06OCT27  0412  34-11  2216  ADC 2 PITOT HEAT CURRENT LOW
06OCT27  0412  30-31  1180  PROBE HEAT 2 FAULT
06OCT27  0947  21-51  0904  PACK 1 OUTLET TEMP HIGH
07OCT27  1135  34-11  0000  ADC 2 SELF TEST PASSED
07OCT27  1302  21-51  0000  PACK 1 GROUND TEST PASSED
```

5. Certificate of release to service

Before release, the certifying engineer confirmed that:

- all tools and equipment were accounted for;
- the deferred defect was entered in the technical log with its expiry date;
- engine ground runs showed no leaks at the oil filter housings;
- the pitot-static leak check on system 2 was within limits.

The work recorded above has been carried out in accordance with the approved maintenance data, and the aircraft is considered ready for release to service.

Certifying engineer: Hemi Walker
Authorisation STS-B1-077

Date and time: 7 October 2027, 14:35 UTC