Task Card: Replacement of No. 2 Engine Bleed Air Valve

Task card no.	TC-26-04417	**Aircraft reg.**	ZK-NWQ
Aircraft type	TP-72 series 600	**MSN**	1418
Station	Elmsford (EFD)	**Date opened**	23 Oct 2026, 07:40 UTC
Reference	AMM 36-11-42-000-801	**Deferral**	MEL 36-11-01 cancelled

1. Reason for Work

The crew of flight NW218 reported a BLEED 2 FAULT caution during the climb from Elmsford. The following ACARS message was received by maintenance control:

```
ACARS DOWNLINK   NWR218   23OCT26 0612Z
FLT NW218  EFD-LMR  FL190
MSG  ENG 2 BLEED FAULT
     BLEED VLV 2 POS DISAGREE
     CMD: OPEN    POS: CLOSED
     BITE CODE 36-11-42  CLASS 2
END MSG
```

Troubleshooting on arrival confirmed that the valve stayed closed when commanded open. The valve is to be replaced in accordance with the reference task.

2. Precautions

- ▲ Make sure that engine 2 has been shut down for at least 30 minutes before you open the cowls.
- ▲ Use heat-resistant gloves when handling bleed ducts and clamps.
- ▲ Keep the work area clear of loose items while the cowls are open.

WARNING: Do not pressurise the bleed system while the duct clamps are loose. Escaping hot air can cause serious injury.

3. Tools and Parts

Item	Part number	Description	Qty	Serial / batch	Issued by
1	BV-3611-07	Valve, engine bleed, pressure-regulating	1	S/N 88214	Stores EFD
2	GK-2270-4	Gasket, V-band flange	2	Batch 26-0915	Stores EFD
3	TW-0150	Torque wrench, 20–150 lbf·in	1	Cal. due 03/2027	Tool crib
4	LW-032	Lockwire, 0.032 in, stainless	A/R	—	Tool crib

4. Procedure

Step	Action	Mech.	Insp.
1	Open circuit breakers ENG 2 BLEED CTL and ENG 2 BLEED VLV on panel 21VU. Fit safety clips and DO-NOT-CLOSE tags.	M-114	—
2	Open the right-hand nacelle cowls and install the cowl hold-open rods.	M-114	—
3	Disconnect the electrical connector from the bleed valve. Cap the connector and the valve receptacle.	M-114	—
4	Remove the two V-band clamps and the valve. Discard the gaskets.	M-114	—
5	Inspect the duct flanges for scoring, cracks and heat damage. Record findings in block 6 of this card.	M-114	I-032

Step	Action	Mech.	Insp.
6	Install the new valve with new gaskets. Position the flow arrow towards the pre-cooler.	M-114	—
7	Install the V-band clamps and torque to 45–50 lbf·in. Tap around each clamp and re-torque.	M-114	I-032
8	Reconnect the electrical connector and lockwire it.	M-114	I-032
9	Close the circuit breakers and run the BITE test from the maintenance panel. Test result: PASS, no fault codes stored.	M-114	I-032
10	Perform an engine ground run at idle with bleed ON. Check for leaks and that BLEED 2 FAULT does not appear.	M-207	I-032
11	Close the cowls and remove all tools, tags and safety clips.	M-207	—

5. Findings

Both duct flanges were found free of cracks and heat damage, with light scoring within the limits of the maintenance manual. The removed valve has been tagged unserviceable and sent to stores with this card number.

6. Return to Service

The work recorded on this card has been carried out in accordance with the approved maintenance data, and the aircraft is fit for release in respect of that work.

Role	Name	Licence / stamp	Date and time (UTC)	Signature
Mechanic	T. Okonkwo-Hale	M-114	23 Oct 2026 10:55	
Mechanic (engine run)	L. Brannigan	M-207	23 Oct 2026 11:40	
Inspector	S. Varga	I-032	23 Oct 2026 11:52	
Certifying engineer	R. Aldous	B1-77412	23 Oct 2026 12:05	

Card closed by maintenance control at 12:10 UTC. MEL item 36-11-01 removed from the technical log.