

BA Repair Rework



Polish bore of shaft until groove is removed; if bore is larger than $\, \phi .382''$, recommend replacing shaft. If larger than $\, \phi .386''$, replace shaft. There may be some pitting in bore of shaft; some small pits are okay and do not have to be removed by polishing.



The BA 201 shaft has Ø.314" bore; replace shaft if worn beyond Ø.323".

