
BJV-M & BJV-P16 Repair Rework

Inspect for groove in seal bore of shaft

Polish bore of shaft until groove is removed; if bore is larger than \emptyset .632", recommend replacing shaft. If larger than \emptyset .636", replace shaft. There may be some pitting in bore of shaft; some small pits are okay and do not have to be removed by polishing.



The BJ 201 shaft has Ø.752" bore; replace shaft if worn beyond Ø.761".

