

glasstech, inc.

Service Bulletin

Customer Service Department

TELEPHONE: 419-661-9000 FAX: 419-661-9639

FCH Hot Fan Maintenance

Reference 011

Insufficient or improper lubrication can be a source of premature bearing failure in the FCH Hot Fan bearings and Hot Fan motor bearings. Under normal, single shift operations, these bearings should be lubricated by adding one pump of grease from a hand grease gun every two weeks. Do not add grease until it comes out at the seals, as this constitutes overlubrication that will result in hot running bearings. For operations that are three shift, seven day a week, lubrication intervals should be reduced to one week.

Grease specifications are a lithium based #2 EP grease. Greases such as Mobil Mobilith AW2, Mobil Grease HP, Shell Alvania 2 or Alvania EP2 are suitable.

Improper belt tension can also cause premature bearing failure. Too loose will induce harmonic vibration, while too tight will result in side thrust loading of motor and fan bearings. Proper tension is when the belts can be deflected by hand approx. ½ inch in the center between the two pulleys.

Belts should also be replaced only in matched sets. Replacing one belt at a time can result in differing belt lengths and tension, and may result in slippage. When replacing belts, always make sure that the pulleys are precisely aligned in the same plane. If they are at an angle to each other, or in a different plane, the belts will be at an angle relative to the grooves in the pulleys. This can lead to throwing belts, or premature belt breakage. It can also put an extra side thrust load on the bearings, contributing to premature wear.