

glasstech, inc.

Service Bulletin

Customer Service Department

TELEPHONE: 419-661-9000 FAX: 419-661-9639

Shuttle Doors and Bender Roofs

Reference 002

1. Ceramic shuttle doors can undergo catastrophic disassembly if the double nut assembly on top of the four vertical rods is allowed to loosen. To prevent this from happening, the top nut should be drilled and pinned to prevent its loosening. Refer to the drawing shown on page two.

2. Inner door seals intended to contact the outside bender sidewall when the door is down can wear out prematurely if the door tracks are incorrectly positioned. The wheels on the ends of the door are intended to be in the "knee" of the 45 degree door track as shown on page 3. The door then comes out away from the bender sidewall $\frac{1}{4}$ inch as soon as it is begun to be raised. If your door tracks are installed so that the inner bender door seal rubs on the sidewall as the door is raised and lowered, the door tracks should be remounted. Redrilling the holes in the C channel track mounts to move the track out and up $\frac{1}{2}$ inch should be sufficient. Keep in mind that the door is intended to seal against the bender at the down position, and have $\frac{1}{4}$ inch clearance from the inner door seal to the sidewall as it is being raised.

3. The bender roof's down position is determined by the position of a large nut and plate at the end of each of four rods located at the four corners of the bender section. These rods are fixed, hanging from the bender superstructure. The bender roof moves up and down, with four collars sliding up and down the rods. To prevent these corner nuts loosening, allowing the bender roof to go down too far, they should be drilled and pinned or a castellated nut and cotter pin arrangement substituted.