

glasstech, inc.

Service Bulletin

Customer Service Department

TELEPHONE: 419-661-9000 FAX: 419-661-9639

INTERNET: <http://www.glasstech.com>

E-mail: service@glasstech.com

SO₂ Usage in FCH Furnaces Reference 034

This document applies to anyone using Sulfur Dioxide (SO₂) in either Glasstech FCH or FCH2 style furnaces.

SO₂ should only be used when a glass-marking problem exists. SO₂ is useful in helping to prevent the adherence of foreign bodies to the ceramic rolls. Excessive use can result in a buildup on the rolls. The use of SO₂ for a brief period each day is often superior to continual application, even at reduced rates.

Note: SO₂ is only effective while the glass is being run through the furnace. Avoid having the SO₂ system on when furnace is in IDLE. DO NOT operate the SO₂ system when the roof is raised and the furnace is not at operating temperature (minimum temperature 400°C)!

If SO₂ is to be used, the following are the proper guidelines for usage in a Glasstech FCH / FCH2 style furnace:

- a) Open the valve on the SO₂ bottle and set the regulator to approximately 103.4kpa (15psi).
- b) Set the flow meter to read 100 for the Black Ball and / or 50 for the Silver Ball. A reading of 100 / 50 on the black / silver ball equals approximately ½ cubic feet per hour of SO₂.
- c) The SO₂ should be applied once per shift for a period of 15 to 30 minutes.
- d) The SO₂ regulator, tubing and couplings should be checked for leakage, using a soap and water solution, on a monthly basis. If any air bubbles are noticed, this indicates a leak and should be repaired immediately.