



Service Bulletin

Customer Service Department

TELEPHONE: 419-661-9000 FAX: 419-661-9639

INTERNET: <http://www.glasstech.com>

Reference #052

Chicago Blower Quench Fan Hub Failures

Glasstech has been informed of a series of fan wheel hub fatigue failures on Chicago Blower size 6600 Series centrifugal fans. These are used in the staged arrangement for glass quenching on select Glasstech side-exit automotive bending & tempering systems delivered to the field between November 2004 and October 2005. Due to the potential danger and the possibility of catastrophic failure, we recommend the following immediate actions:

1. Immediately inspect the four quench fan wheels and hubs using visual means through the inspection hatch provided on the fan housing. The reported failures have been cracking of the cast hub and the fabricated impellor (see photos & sketch on page 2 of this document).
2. If cracks are identified with a visual inspection, a follow-up inspection using a dye penetrate test should be conducted. Removal of a housing section from the fan may be required to gain access for optimal viewing, particularly on the drive side of the hub.
3. If cracks are identified, operation of the suspect fan(s) should be immediately suspended. Depending on the location and/or severity of any cracks that are found, Chicago Blower recommends that repair or replacement of the hub be completed. The fan bearings should also be inspected and replaced as necessary.
4. The vibration sensors provided with the fans should be inspected by a qualified electrician to ensure that these safety devices are in proper working order and will provide both alarm and shutdown actions in the event of an excessive vibration condition.

For further assistance, please contact Chicago Blower Corporation who can be contacted via telephone at the their corporate offices in Glendale Heights, Illinois at +1.630.858.2600 or by contacting their web site at www.chiblo.com

CONTINUED ON NEXT PAGE

