Monkey Nut, LLC.

4221-A Joe Street Charlotte, NC 28206 704.598.6219

parts@monkeynutvw.com

Invoice

Date	Invoice #	
6/22/2016	MN-7026	

06.22,2016

Ship To

Bill To	
Matthew Greenwald 80 Haven Ave Apt 1C New York City, NY 10032	ger,

				<u> </u>		
Item	Description	Qty	U/M	Rate	Amount	
2016 Labor Rate	- remove spark plugs - put bus on jack stands - looked engine over for exhaust leaks - compression test: #1-35 psi #2-105 psi #3-50 psi #4-110 psi - leak down test: #3 leaking badly between county and head - reinstall #3 cylinder rocker shaft and valve - replace spark plugs and wires and air box, in Used 1 new valve cover gasket -removed oil pressure switch -conducted oil pressure test: 25 psi cold idle-50psi at 2500 rpm cold -6 psi warm oil pressure and 28 psi at 2500 removed sticker/decals from sides of bus Notes: -Leak down and compression tests indicate a end rebuild is needed Oil pressure test indicate the bottom end of motor has high mileage, but is not worn out. Certainly could use a bottom end rebuild, bu get away without it Recommend replacing the exhaust with a nestainless steel unit	top the		85.00 85.00		.00T

Subtotal	\$425.00
Sales Tax (7.25%)	\$30.81
Total	\$455.81
Payments/Credits	-\$455.81
Balance Due	\$0.00