WavetableController Rev 4 — Final Red-Flag Report

Date	2026-10-13
Inputs	Rev-4 KiCad project (board with filled GND pour), BOM and Gerbers, sent by Trey 2026-10-13 (`rev4/`)
Baselines	Rev-3 review (`analysis/rev3/`, 65 entries) · 7 October "Rev 2 Design Review" rows · post-rev-3 chat decisions (LED values, /+9V_FLAG re-pointing, encoder RC, SD caps, inrush)
Scope	Passes 0–6 complete · 57 rev-4 ledger entries (`FINDINGS.md`) · every rev-3 finding re-scored · every Oct-7 row re-scored (`OCT7_REVIEW_STATUS.md`)
Truth	The rev-4 `.kicad_pcb` is copper truth; Trey's Gerbers agree with it on every number; nothing has been fabbed from rev 4
Verification	55 of 57 entries confirmed by script against the files; 1 plausible, waiting on Trey (pot taper); settled facts not re-opened

Decisions recorded after the passes ran (Kyle, 2026-10-13)

- The screen is **not mounted in this build** → Oct-7 row 5 is deferred.
- The LEDs are **hand-soldered Würth 150505M173300** (part already approved) → the missing BOM line is paperwork, not an assembly gap.
- The encoder filter caps **at the encoder end are accepted** (no room near the Seed; better than none).

Headline

Rev 4 is a targeted patch of rev 3, not a re-layout. Outside the changed parts the copper is identical to the millimetre: same 74.9 mm of 0.1 mm trace, same pour fragments, same SPI / SD / USB / MIDI / audio routes, same J8, same holes. Inside the patch Trey closed most of what was open after rev 3.

Oct-7 row	Rev 3	Rev 4
2c — U6 fed ahead of the 3.3 Ω filters	NOT DONE	**DONE** — LED/buck node ≈ 8.1 V, independent of the display
3c — LED resistors 510 Ω red / 390 Ω green-blue	NOT DONE	**DONE** — 11.6–12.1 mA, 57–69 mW in 0603
6b — L1 on the Murata DFE201610P pattern	NOT DONE	**DONE**
7 — Encoder 10 k pull-ups + 10 nF caps	NOT DONE	**DONE** — caps at the encoder end, accepted
9 — Delete D6; bridge to SOD-123FL	NOT DONE	**DONE** — 1N5817W, IFSM 25 A
SD-socket caps	NOT DONE	**DONE** — 10 µF at 5.2 mm, 100 nF at 6.9 mm from P1 VDD
5 — J8 position + four M2 holes	NOT DONE	**DEFERRED** — screen not mounted in this build
3d — LED part name / BOM line	DOCUMENTATION	**DOCUMENTATION** — hand-soldered Würth confirmed
Fab-margin rows (5) and tidy items	NOT DONE	**NOT DONE** — see Tiers 3 and 4

Nothing on the Oct-7 fix list blocks ordering rev 4. Of the 65 rev-3 findings: 4 fixed, 20 re-pass, 4 settled, 37 still open. None regressed; one got a pad worse (a ninth single-spoke GND thermal, on the new SD cap).

Tier 1 — Worth fixing before ordering (judgment; nothing here is a fab rejection)

1. Ground stitching — zero stitching vias; an easy fix and cheap insurance against noise

(R4-P1-08 · first raised in the rev-3 review, not on the 7 Oct list)

- **What it is:** everything on the board **is** connected to ground (DRC: 0 unconnected items). The issue is how the two ground layers join each other. The bottom ground fill is one sheet; the top ground fill is chopped into 15 separate patches by the tracks crossing it. Normally stitching vias every centimetre or so tie each top patch to the bottom sheet. This board has 253 vias and not one is on ground: a top patch touches the bottom sheet only where a component's through-hole pin passes through both, and three patches rely on a single pin for that. The same 10 IC/cap ground pads (U2, U3, U4, U6) reach ground by one thin track, and nine ground pads have a single thermal spoke (the new C28 joined that list).
- **Why it matters:** a signal running on the top layer wants its return current in the ground patch directly underneath. If that patch has only one way back to the main sheet, the return detours, and the detour is what couples noise between circuits.
- **Potential consequence:** hum or a faint digital hash in the headphones, worst around the audio section and the buck converter. Not a dead board; the rev-1 boards worked without it.
- **Fix:** a few minutes in KiCad — add GND vias (0.6 / 0.3, like the rest) in every top-side ground patch, especially the three single-pin ones, and next to the U2 / U3 / U4 / U6 ground pads; set the zone's minimum spokes to 2 or add a short GND track on the nine single-spoke pads.

2. Inrush — no series resistor before C15; smaller than rev 3, but not limited

(R4-P2-05 · decision 5e not applied · first raised in the rev-3 review, not on the 7 Oct list)

- **The exact scenario:** the unit is off, so the 100 µF capacitor C15 holds no charge. The 9 V adapter is plugged in, or SW1 is flipped. For the first few microseconds an empty capacitor behaves like a short circuit, and the current that rushes in is limited only by what is in the path: the adapter's output, the barrel-jack contacts, the switch contacts, two diode drops and three ferrite beads at 0.05 Ω each. That is roughly a quarter of an ohm, so a peak of up to ≈ 30 A for ≈ 25 µs from a stiff adapter (an upper bound; a real adapter's output impedance lowers it).
- **What it does not hurt:** the diodes (the 1N5817W's 25 A rating is for an 8 ms pulse; this one is 300× shorter) and the adapter (it sags briefly).
- **Potential consequence:** the switch and jack contacts are the wear item. Each power-on puts a small spark across them as they close, and the slide switch does it several times per flip because of contact bounce. Over hundreds of cycles that pits the contacts; the symptom is a supply that drops out when the unit is bumped or the switch is wiggled. A slow failure, not a day-one one. Rev 1/2 never had this (10 µF at the input); rev 3 added 700 µF; rev 4 cut it to 310 µF, but the 100 µF directly on the unprotected path remains, and removing D6 and FB7 took 0.45 V and 50 mΩ out of the path.
- **Fix:** one part — a 1 Ω, 1 W resistor between FB5 and C15 (or an NTC). Peak drops to ≈ 8 A; cost 0.45 V and 0.2 W at full load; Daisy VIN still ≈ 7 V, inside 4–17 V. Can go in the next spin if not this one.

If only one of these two is fixed for this build, make it the ground vias.

Acknowledged / deferred by decision (Kyle, 2026-10-13)

Display mounting (Oct-7 row 5 · R4-P6-05)

- **Status:** "Acknowledged — will potentially deal with later." The screen is not mounted in this build.
- **What stands:** J8 is where it was; no M2 holes for the NHD module, no chassis holes for the board.
- **Potential consequence if the module is fitted later as-is:** it hangs on 20 solder joints behind the panel window until the holes exist; the enclosure window position stays open.

LED bookkeeping (R4-P4-01 · R4-P2-03 · R4-P6-04)

- **Status:** Trey hand-solders Würth 150505M173300; polarity and footprint are right for it. No assembly gap.
- **What stands:** schematic Value still "CLS6B-FKW" with the Cree pin labels; no hand-solder sheet.
- **Potential consequence:** the next person reading the files reaches the wrong part and the wrong polarity conclusion, as this review did in rev 3.
- **Fix (paperwork):** Value → 150505M173300, relabel the symbol pins, add a hand-solder sheet.

Encoder filter caps (Oct-7 row 7 · R4-P3-03 · R4-P5-04)

- **Status:** accepted as built — no room near the Seed.
- **What stands:** the four 10 nF caps sit at the encoders on the back, 6.8–10.2 mm from the encoder pins and 63–111 mm from the Daisy pins.
- **Potential consequence:** contact bounce is filtered at the source (good); the MCU input stays on an unterminated 63–111 mm line (noise pickup along the run). Keep the state-table quadrature decoder in firmware.

Tier 2 — Robustness items, half done or unchanged

3. Decoupling: SD socket fixed, headphone amp still bare

(R4-P2-06 · R4-P2-07 · R4-P2-08)

- **Done:** C28 10 µF and C27 100 nF now sit 5.2 / 6.9 mm from the SD socket's VDD pin — the rev-3 "120 mm to the nearest cap" item is closed.
- **Not done:** the optional second 10 µF at Daisy pin 38 (C28 is 27.9 mm from it — acceptable); the TPA6110A2 headphone amp still has only 100 nF on its 3V3_A rail, third revision running (F-031).
- **Potential consequence:** distortion or a faint whine into long headphone leads; the mic amp shares the same under-filtered rail.
- **Fix:** 10 µF (or more) on /+3V3_A at U3.

4. Digital traces beside audio traces, unchanged

(R4-P5-02 · R4-P5-03)

- **What stands:** /USART1_RX runs 49 mm beside AUDIO_IN_L at 0.41 mm, /USART1_TX 26 mm at 0.45 mm; **/TAC_SWITCH_2 runs 27 mm beside AUDIO_OUT_R at 0.20 mm** (and 32 mm beside AUDIO_OUT_L at 0.70 mm) — the closest pairing on the board, same layer.

- **Potential consequence:** a tick on the audio input on MIDI traffic; a click on the line out when the right tactile switch is pressed.
- **Fix:** move the UART and the TAC_SWITCH_2 trace ≥ 1 mm from the audio lines, or put them on the other layer.

5. /RES_SPI floats until firmware drives it

(R4-P3-05 · unchanged from rev 3)

- **What stands:** the OLED reset line is a bare two-node net with no pull-up or RC.
- **Potential consequence:** the display's reset state is undefined from power-up until the firmware configures the pin — usually invisible, occasionally a garbage first frame or a display that needs a second init.
- **Fix:** 10 k from /RES_SPI to /+3V3_OLED.

Everything else in this tier is as rev 3: SPI lines unterminated but electrically short (optional 22–33 Ω or GPIO slew ≤ medium), USB pair length-matched but via-heavy, audio runs long but 0.3 mm — residual judgments, no action required.

Tier 3 — Fab margins (all five Oct-7 rows still NOT DONE)

Item	Measured	Limit	Potential consequence if left	Fix
MK1 annular ring (R4-P1-02)	0.175 mm (1.0 pad / 0.65 drill)	JLCPCB 0.18 absolute, 0.25 recommended	A stricter lot rejects the order, or a thin ring breaks out and the mic pin lifts. Fabbed OK twice so far	MK1 pads 1/2 → 1.1–1.2 mm
USB-C NPTH-to-GND-pad (R4-P1-03)	0.197 mm	0.20 mm	3 µm under: DFM rejection or a drill break-out into the GND pad possible. Fabbed OK twice	Shrink A1/A12/B1/B12 by 0.05 mm
U6 thermal vias (R4-P1-04)	0.25 mm drill / 0.60 pad	Legal at JLC; project rule says 0.30	Extra drill tool; trips the project's own DRC so real errors hide among known ones	Footprint EP vias → 0.30 / 0.70
Silk outlines (R4-P6-02)	0.12 mm stroke; refdes exactly 1.0 / 0.15	0.15 mm line	Outlines print faint or are dropped. Cosmetic	Footprint outline width 0.15
DRC minimums (R4-P1-12)	`min_track_width 0.0`, `min_clearance 0.0` (`.kicad_pro` identical to rev 3)	—	KiCad never warns about sub-minimum copper; the next thin trace ships unnoticed	Board Setup → Constraints: 0.1 / 0.1
0.1 mm copper (R4-P1-01)	74.9 mm, unchanged (U4 fan-out, U6 EP, USB, 5.9 mm /USART1_TX)	0.10 mm, ±20 %	Zero margin where it remains; DRC at JLC minimums is otherwise clean	Widen the USART/USB/3V3_A bits to 0.15 where room exists

---

Tier 4 — Hygiene

Item	State in rev 4	Potential consequence if left	Fix
ERC flags (R4-P3-06 · R4-P2-11)	14 missing no-connect flags + 4 missing PWR_FLAGs; ERC 51 items, identical to rev 3	A real wiring error hides among 20 known false errors on the next revision	NC flags on P2 SS/SBU pins and J8 3/9/15/18; PWR_FLAG on /DSY_VIN, /+9V_FLAG, Net-(U4-VDD), GND
Hand-assembly sheet (R4-P4-03)	One-sheet BOM; 18 THT parts + the hand-soldered LEDs listed nowhere	A board passes assembly and fails on the bench because a through-hole cap or the LEDs were never fitted	Second BOM sheet with value, footprint, net and source for every hand-fitted part
Position-file flags (R4-P4-04)	"Exclude from position" only on J3–J7; 15 CPL rows with no BOM match	JLC upload shows 15 unmatched entries; harmless but noisy	Set the flag on all THT parts
BOM cell hygiene (R4-P4-05)	Numeric footprint cells, mojibake, one stale cell (D2–D5 say "SOD-323" for the SOD-123FL part ordered)	None at JLC (keys on LCSC #); confuses a human reader	Tidy the cells; fix the D2–D5 text
Refdes repurposed (R4-P4-06)	C19–C22 100 µF → 10 nF, R31/R32 3.3 Ω → 10 k between rev 3 and rev 4	Any rev-3 note, photo or rework instruction naming them now points at a different part	One line in the change log; renumber instead next time
Extended parts (R4-P4-07)	U6, L1, R4, R29/R30, R35–R40, C3339 ×5, D2–D5	Per-line handling fees; R35–R40 is avoidable (C21190 1 % is Basic)	Swap R35–R40
Dangling vias (R4-P1-07)	2, on /LED_2_R and /LED_2_B, unchanged	Two needless holes; cosmetic	Delete
Back-side artwork (R4-P6-01)	3,900 polygons bury 97 of 104 bottom refdes; runs off all edges; nothing on a pad	Inspection and rework harder; assembly unaffected	Refdes halo, or move refdes to Fab
Headphones1 (R4-P3-07 · R4-P6-07, waiting on Trey)	Linear (B) taper as volume control; rotation sense unverified; bushing 9 mm outside the outline	Volume may run backwards or feel wrong; panel needs a cut-out	Trey to confirm; prefer A-taper
SD card detect (R4-P3-09)	/SWA single-pin; all 40 Daisy pins used	Card presence unreadable by firmware	Pin trade if the feature is wanted
SW1 contact code	Not on the JLC BOM, unverifiable	A logic-level (gold 0.4 VA) contact pits at 0.5 A and goes intermittent	Check the ordered part is 1101A4VQEA with silver 5 A contacts

What passed (verified, cited)

- Schematic ↔ PCB 112 / 112 parts, 0 net differences, 0 duplicate refdes.
- BOM ↔ schematic ↔ PCB 92 / 92 three-way; values 92 / 92; the four new LCSC numbers verified by part page; the new bridge part fits its pads.

- U6 fed from the FB6 node at ≈ 8.1 V (3–17 V window); TPS62172 loop unchanged; L1 on the Murata pattern.
- LED currents 11.6 / 12.1 mA, 57–69 mW in 0603; polarity correct for the Würth part; 3.3 V-only Daisy pins behind 1 kΩ bases.
- D6 and FB7 gone; 1N5817W bridge on matching pads; Daisy VIN 6.8–7.5 V; grounds tied; reverse polarity by the bridge; IPC-2221 ampacity on every rail.
- SD socket decoupled; encoder pull-ups and caps wired and routed; encoder clicks routed.
- J8 wiring = NHD serial pin table 20 / 20; 4-wire SPI strap; NC pins correct.
- DRC at JLCPCB minimums: 0 clearance / width / edge / drill errors; courtyards, outline, mask, hole spacing clean.

Question for Trey

- **Headphones1:** is CW = louder as wired, and is a linear taper intended? (carried from rev 3)

Threshold-source caveats

As rev 3: Daisy, Cree and Murata hosts blocked from this session; Daisy pin facts from the KiCad symbol and libDaisy; SSD1322 10 MHz from memory. JLCPCB capabilities and the four new part pages fetched live 2026-10-13.