Incident Communication Pack: Executive Summary and Dashboards

Model: VFIP-GD-EXEC-COMMS-2025 | Category: Guides | Incident: XG-440 Firmware Rollout

Table of Contents

1. Executive One-Page Summary
2. Impact Metrics & Financial Summary
3. Timeline Highlights (Day-by-Day)
4. Vendor Firmware Release Notes (v3.14.2 → v3.15.0)
5. Vendor Change Tickets & Rollout Scope
6. O&M Incident Report & Postmortem
7. Dispatch Runbooks & SCADA → CMMS Mapping
8. Settlement & Imbalance Charge Guidance (ERCOT)
9. Dashboard Components & Slide Text
10. Talking Points and Questions for Asset Performance Analyst
11. Appendix: Codes, Field Names, Procedures

1. Executive One-Page Summary

This pack provides the CIO and leadership a concise, data-driven briefing on the XG-440 firmware incident affecting firmware releases **v3.14.2 through v3.15.0**. It includes a one-page incident summary, financial impact, timeline highlights, recommended immediate actions for vendor escalation and temporary operating mitigations, and descriptions of dashboard surfaces to present the situation.

Headline

Firmware change introduced between v3.14.2 → v3.15.0 caused increased protective trips under high-frequency deviation and reactive-power excursions impacting a subset of XG-440 inverters. Net generation loss for the event is estimated at **net MWh loss: 4,200 MWh**. Financial impact: **$1.42M merchant revenue loss** and **$260K O&M and restoration costs**. The event window with most impact: 2025-12-07 03:00 UTC – 2025-12-09 15:00 UTC.

Immediate asks for leadership

- Authorize vendor escalation call with CTO and senior vendor firmware lead within 2 hours.

- Approve emergency rollback of affected inverters to known-good firmware v3.14.1 for critical serial ranges (see Change Ticket section) pending vendor hotfix verification.
- Approve temporary operating mitigations: adjust reactive setpoints, raise trip thresholds for TRIP-31 and TRIP-44 on non-critical sites, and enable manual dispatch curtailment avoidance window where safe.

2. Impact Metrics & Financial Summary

Summary metrics calculated by the asset performance team using SCADA 5-minute generation values, EMS dispatch logs, and settlement data.

Metric	Value	Notes / Calculation
Net Energy Lost (MWh)	4,200 MWh	Difference between actual generation and 30-day baseline (normalized by irradiance and temperature) 2025-12-07 → 2025-12-09.
Merchant Revenue Impact	$1,420,000	Sum of lost energy priced at day-ahead cleared price adjustments and some bilateral PPA penalties (calculation in Appendix).
O&M & Restoration Costs	$260,000	Labour, hotfix rollout labor, travel, and temporary local site support for rollback.
Number of Affected Inverters	1,140 units	Serial ranges and site lists in Change Ticket section.
Main Protective Trips Observed	TRIP-31, TRIP-44, TRIP-07	TRIP-31: frequency over/under threshold; TRIP-44: reactive limit; TRIP-07: DC voltage anomaly.

Key Assumptions

- Baseline generation: 30-day normalized rolling average with weather correction using SCADA pyranometer and cell temperature regressors.
- Settlement price assumptions: day-ahead nodal prices where applicable and real-time where not pre-scheduled; imbalance exposure per ERCOT settlement rules (see settlement section).

3. Timeline Highlights (Day-by-Day)

2025-11-20 – Vendor Rollout Start

Vendor initiated staged rollout of firmware v3.14.2 across initial small cohort.

Change ticket CT-2025-1120-ROLL documented. No material incidents reported.

2025-11-21 – Rollout Expansion

Vendor expanded rollout to broader set via CT-2025-1121-ROLL. Scope included serials XG440-10000 → XG440-10500 and XG440-11000 → XG440-11200 at 5 plants. Minor increase in TRIP-44 occurrences reported; vendor monitoring.

2025-12-07 – First Major Event

Between 03:00 – 08:00 UTC spike in frequency deviations recorded across ERCOT; inverters with v3.14.2 began generating repeated TRIP-31 and TRIP-44 protective trips. SCADA shows ramp-downs and auto-reconnect delays.

2025-12-08 – Hotfix Issued

Vendor published hotfix v3.15.0 as an attempt to address trip sensitivity. A hotfix rollout change ticket CT-2025-1208-HF opened. Immediately following hotfix deployment, increased TRIP-07 occurrences observed in a subset of serial ranges (hotfix regression).

2025-12-09 – Widespread Curtailment & Impact

Event window culminated 03:00–15:00 UTC with observed total generation loss and multiple site-level curtailments. Operations enacted temporary mitigations; vendor recommended rollback if TRIP-07/44 continued.

Validation Steps Conducted

1. Cross-check SCADA event logs against inverter internal protected-trip logs (serial-level) using vendor-supplied diagnostic export.
2. Weather-normalized baseline comparison for energy loss.
3. Settlement data reconciliation for imbalance exposure (see Settlement Guidance).

4. Vendor Firmware Release Notes (v3.14.2 → v3.15.0)

The vendor (XG-Controls) release notes below are reproduced from portal exports and annotated for operational clarity. Fields included: version, release date, change summary, configuration parameter names, protective trip codes, and recommended rollback conditions.

Version: v3.14.2 (Release Date: 2025-11-20)

Field	Detail
Change Summary	Minor performance improvements and tuning of frequency ride-through thresholds.

Parameters Modified	- freqROThr_Hi -> previously 60.75 Hz; updated to 60.70 Hz - freqROThr_Lo -> previously 59.25 Hz; updated to 59.30 Hz - reactiveLimitPct -> default 105% -> 100%
Protective Trip Codes Affected	TRIP-31 (frequency R-FRT sensitivity increased), TRIP-44 (reactive clamp).
Rollback Recommendation	Rollback to v3.14.1 if unexplained increase in TRIP-31 events > 1% of fleet within 24 hours.
Notes	Applied to alpha cohort only; advanced diagnostics flag added: DIAG-FRT-LOG (exports on request).

Version: v3.15.0 Hotfix (Release Date: 2025-12-08)

Field	Detail
Change Summary	Attempt to reduce spurious FRT trips by adding hysteresis and delay in protective logic; also adjusted DC over-voltage detection thresholds.
Parameters Modified	- freqRODelay_ms -> added default 500 ms (was 150 ms) - reactiveHyst_pct -> added 3% hysteresis window - dcOV_TripV -> increased from 880 V -> 904 V
Protective Trip Codes Affected	TRIP-07 (DC anomaly), TRIP-31 (frequency), TRIP-44 (reactive). New diagnostic: DIAG-OV-HYST.
Observed Regression	Sites with older DC cabling reported increased TRIP-07 occurrences; vendor notes potential unintended side effect of dcOV_TripV change.
Rollback Recommendation	Rollback immediately if TRIP-07 rate > 0.5% of events or if inverters show >3 consecutive auto-reconnect failures.

Operational Guidance (Vendor)

- Enable DIAG-FRT-LOG and DIAG-OV-HYST exports for affected serial ranges and provide to vendor support bundle within 2 hours of request.
- Vendor recommends staged rollback to v3.14.1 for critical serial ranges when persistent trip thresholds observed.
- Vendor-provided CLI parameter names for immediate operator changes (requires reboot): set reactiveHyst_pct=1.5 ; set freqRODelay_ms=300 (temporary).

5. Vendor Change Tickets & Rollout Scope

Change ticket extracts from vendor portal. Each ticket includes scope by plant and serial ranges and a short remediation history.

CT-2025-1120-ROLL — Initial Rollout (2025-11-20)

Field	Detail
Scope	Plant: Mesa Ridge (PLANT-A); Serial ranges: XG440-10000 → XG440-10150
Rollout Type	Staged (10% per hour)
Validation	Per-device health check via DIAG-FRT-LOG; collected 48 hour health reports.
Outcome	No critical escalations.

CT-2025-1121-ROLL — Expanded Rollout (2025-11-21)

Field	Detail
Scope	Plant: Mesa Ridge (additional), Sunvale (PLANT-B), Riverbend (PLANT-C); Serial ranges: - XG440-10151 → XG440-10500 (PLANT-A) - XG440-11000 → XG440-11200 (PLANT-B) - XG440-11500 → XG440-11700 (PLANT-C)
Rollout Type	Canary to bulk over 48 hours
Outcome	Increase in TRIP-44 reported at PLANT-B (5% of inverters flagged for review).

CT-2025-1208-HF — Hotfix Deployment (2025-12-08)

Field	Detail
Scope	Hotfix v3.15.0 targeted at all inverters with v3.14.2 and v3.14.3 (serials XG440-10000 → XG440-12000).
Scope Exceptions	Excluded older hardware revision revA (serials XG440-10000 → XG440-10100) flagged for manual testing.

Observed Side-Effects	Regression causing TRIP-07 at sites with older cabling and higher DC voltage variability.
Recommended Remediation	Immediate rollback for affected serial range XG440-10220 → XG440-10340 pending vendor analysis.

> **Operator action:** Use CMMS work order template WO-FW-ROLL-EMERG for rollback tasks. Ensure diagnostic bundle DIAG-BUNDLE-*SERIAL*.zip is attached to each ticket.

6. O&M Incident Report & Postmortem

Consolidated postmortem for the O&M organization covering the root cause analysis, containment, corrective actions, and preventive actions.

Executive Summary

Root cause: Firmware parameter tuning in v3.14.2 increased frequency ride-through sensitivity and reactive clamp that, in specific grid conditions, initiated protective trips (TRIP-31, TRIP-44). Hotfix v3.15.0 attempted to mitigate but changed DC over-voltage behavior causing TRIP-07 regressions. Contributing factors include incomplete fleet segmentation, insufficient field cabling variance tests, and lack of early rollback criteria enforcement.

Day-by-Day Timeline (Detailed)

1. **2025-11-20:** v3.14.2 applied to alpha cohort. Diagnostics enabled.
2. **2025-11-21:** Expanded rollout; early TRIP-44 uptick observed at PLANT-B. Vendor monitoring ticket opened.
3. **2025-12-07:** Grid events triggered increased TRIP-31 occurrences; automated disconnects observed with delayed auto-reconnect.
4. **2025-12-08:** Hotfix v3.15.0 deployed. Post-hotfix regression TRIP-07 reported on 2025-12-08 18:30 UTC.
5. **2025-12-09:** Manual mitigations applied; rollback initiated for high-impact serial ranges; vendor support prioritized.

Containment and Recovery

- Immediate rollback of serials XG440-10220 → XG440-10340 to v3.14.1 completed 2025-12-09 23:00 UTC.
- Temporary operating mitigations deployed: increase freqRODelay_ms to 350 ms on non-critical sites, set reactiveLimitPct to 110% where grid-stability allows.
- Field crews executed staged restarts and inspections; 72-hour monitoring period enforced.

Root Cause Analysis

Primary cause: parameter changes in v3.14.2 not validated across hardware revisions and real-world DC cabling conditions. Secondary cause: hotfix v3.15.0 modified DC over-voltage thresholds without full regression testing.

Corrective Actions (Immediate)

1. Rollback prioritized to v3.14.1 for affected serial ranges by plant.
2. Require vendor to supply a verified hotfix candidate with full regression matrix across HW revisions within 7 days.
3. Enable mandatory DIAG-FRT-LOG and DIAG-OV-HYST exports before any future bulk rollout.

Preventive Actions (Longer-term)

- Revise rollout policy: require staged canary > 72 hours and automated trip-rate threshold that triggers automatic halt.
- Improve fleet segmentation records in CMMS including hardware revision and cabling type.
- Update acceptance criteria: include DC cable variance and field wiring simulation in vendor QA.

7. Dispatch Runbooks: SCADA Alarms → CMMS Corrective Work Orders

Standardized mapping to accelerate field dispatch and ensure consistent tracking.

Alarm to Work Order Mapping Table

SCADA Alarm	Alarm Code	Immediate Action	CMMS WO Template	Notes (Fields)
Inverter TRIP-31 (Freq FRT)	ALM-TRIP31	Tag device offline, manual reset if safe, capture inverter trip log.	WO-FRT-RESET	Fields: serial, timestamp, gridFreq, tripCount, DIAG-FRT-LOG link
Inverter TRIP-44 (Reactive Limit)	ALM-TRIP44	Apply temporary reactiveLimitPct override to safe value; monitor for re-occurrence.	WO-REACTIVE-ADJ	Fields: reactiveLimitPct_pre, reactiveLimitPct_post, plant, serialRange

Inverter TRIP-07 (DC OV)	ALM-TRIP07	Isolate inverter from AC if repeated; log DC voltage traces; initiate site inspection.	WO-DC-INSPECT	Fields: DCVolts_trace, cableRevision, lastFirmware, safetyLockout

Work Order Template Examples (Fields & Values)

```
WO-ID: WO-FRT-RESET-YYYYMMDD-
PRIORITY: P1
SITE:
ASSET: Inverter XG-440 / Serial:
SYMPTOM: ALM-TRIP31 reported at
DIAG FILE: DIAG-FRT-LOG--.zip
STEPS:
  1) Confirm grid frequency from SCADA snapshot.
  2) Download inverter log (DIAG-FRT-LOG).
  3) If single trip within 15 minutes and reconnects: monitor 24 hours;
  4) If >3 trips or no reconnect: schedule field visit within 12 hours.
CLOSE NOTES: Include field voltage readings and final firmware version.
```

Emergency Dispatch Flow

1. SCADA Alarm triggers ALM-TRIPXX. Dispatcher creates CMMS WO using template.
2. Dispatcher notifies on-call O&M engineer and vendor support (escalation list in Appendix).
3. Vendor and O&M examine DIAG bundle; decide on rollback or field visit.
4. Field crew uses WO checklist; confirms action; updates WO with diagnostic attachments.

8. Settlement & Imbalance Charge Guidance (ERCOT)

This section explains how penalties and imbalance charges are calculated in ERCOT and which data fields must be reconciled during the incident.

Key Settlement Concepts

- Settlement Interval: 5-minute intervals for real-time and day-ahead settlement.
- Imbalance Charge: Occurs when actual generation differs from scheduled (day-ahead or bilateral) quantities; charges are calculated

using real-time prices and potential ancillary services costs.
- Settlement Data Sources: ARR (ancillary), RTSETTLE, DASETTLE, and SCADA energy telemetry.

Important ERCOT Fields to Reconcile

Field Name	Source	Purpose / Note
IntervalDateTime	RTSETTLE	5-minute timestamp for settlement interval
ScheduledMW	DASETTLE / Bilateral	Quantity expected to be produced
ActualMW	SCADA / Telemetry	Measured generation (must check SCADA validity flag)
ImbalancePenalty	RTSETTLE	Calculated charge for deviation
AncillaryCharges	ARR	Possible additional charges if services procured

Step-by-Step Reconciliation Procedure

1. Export SCADA raw 5-minute ActualMW for the event window and mark invalid flags (SCADA field: qualityFlag).
2. Obtain scheduled positions (PPA and DA) for the same intervals. Field: ScheduledMW (source: DASETTLE).
3. Calculate interval-by-interval deviation: DeltaMW = ScheduledMW - ActualMW. Sum positive deltas for lost generation; negative deltas for over-generation.
4. Apply settlement prices: For each interval, ImbalanceCharge = DeltaMW * RTPrice. RTPrice from RTSETTLE.PriceNode or nodal price mapping.
5. Sum ImbalanceCharge across intervals to compute merchant exposure. Compare to pre-computed estimate ($1.42M).
6. Reconcile ancillary charges if there were frequency response procurements triggered by trips (check ARR dispatch events and service flags).

Common Data Quality Issues & Troubleshooting

- Time skew between SCADA and settlement timestamps — ensure time zones and DST are normalized to UTC.
- Missing SCADA intervals — use interpolation only for short gaps (<15 minutes); document any interpolation in settlement dispute.
- Telemetry qualityFlag indicates sensor error — request telemetry reprocessing and validate against inverter power meter logs.

9. Dashboard Components & Slide Text for Executive Briefing

Designs and recommended slide text for executive dashboards emphasizing clarity and rapid situational awareness. Dashboard components are intended for inclusion in the executive one-pager and slides.

Dashboard 1: Availability by Equipment Type and Model

Purpose: Show fleet-level availability filtered by model and hardware revision to identify affected cohorts.

Widget	Data Fields	Visualization
Availability Summary	Model, HWRevision, AvailableMW, RatedMW, Availability%	Stacked bar chart by model with availability percent labels
Top Affected Serial Ranges	SerialRange, TripCount, LastTripTimestamp	Table with sorting

Slide text (one-line): "Availability impact concentrated in XG-440 revA units; immediate rollback executed for the most affected serial ranges."

Dashboard 2: Daily Net Generation vs 30-Day Baseline

Purpose: Quantify daily energy loss and illustrate deviation from expected generation.

Widget	Data Fields	Visualization
Daily Net Generation	Date, ActualMWh, BaselineMWh, WeatherNormalized%	Line chart overlay with shaded deviation area
Per-Plant Deviation	PlantID, DeltaMWh, Delta%	Small multiples or heatmap

Slide text (two lines): "Cumulative energy loss of 4,200 MWh vs 30-day baseline (weather-normalized). Major contributors: PLANT-B and PLANT-C during 2025-12-07 → 12-09."

Dashboard 3: Cumulative Lost Revenue and Penalties

Purpose: Show financial impact over time, including merchant revenue loss and O&M cost accruals.

Widget	Data Fields	Visualization

Cumulative Loss	Date, CumulativeMerchantLoss, CumulativeOMCost, TotalLoss	Stacked area chart
Interval-level Penalties	IntervalDateTime, PenaltyAmount, Source (RT/DA/Ancillary)	Bar chart or table

Slide text (one-line): "Total estimated short-term impact: $1.42M merchant + $260K O&M (validated against RTSETTLE and SCADA reconciliation)."

Dashboard Implementation Notes

- All dashboards should include a filter for FirmwareVersion and SerialRange for ad-hoc drilldowns.
- Include export links to DIAG bundles and CMMS WO attachments on each plant detail page.
- Show confidence bands on baseline estimates indicating +/- uncertainty (explicit numeric values, e.g., ±6%).

10. Talking Points and Questions for Asset Performance Analyst

Prepared questions and data requests for the briefing with the asset performance analyst to support leadership Q&A.

Immediate Briefing Questions

1. Confirm the current count of offline inverters by serial range and plant (please provide CSV with fields: plant, serial, lastSeenUTC, lastFirmware).
2. Show the interval-level net MWh loss by plant for the incident window (CSV with interval, plant, actualMW, baselineMW, deltaMW).
3. Provide the top 10 intervals by penalty amount and the source of the penalty (RT vs DA vs Ancillary).
4. Confirm rollback status: list serial ranges already rolled back and those pending with expected completion timestamps.
5. Has the vendor provided a reproducible test case for TRIP-31/TRIP-44? If so, provide test logs and pass/fail criteria.

Follow-up Data Requests

- Attach DIAG-FRT-LOG exports for 100 representative serials across HW revisions.
- Telemetry quality report for all intervals with deltaMW > 0.5 MW (fields: qualityFlag, sensorSource).
- CMMS WO status export for all WO-FW-ROLL-EMERG and WO-DC-INSPECT generated during the event.

Suggested Executive Framing

“We executed vendor challenge/rollback and mitigations; the incident is contained but we will continue fleet stabilization and settlement reconciliation. The immediate priority is ensuring a stable patch candidate and closing the verification criteria for full fleet redeployment.”

11. Appendix: Codes, Field Names, and Procedures

Reference material for RAG and knowledge assistant ingestion: code tables, field lists, and compact procedures suitable for automated agents.

Protective Trip Codes

Code	Name	Trigger Conditions	Action
TRIP-31	Frequency Ride-Through	Grid frequency outside tripod thresholds or sustained excursion per freqRODelay_ms	Disconnect; generate DIAG-FRT-LOG
TRIP-44	Reactive Limit Clamp	Reactive power beyond reactiveLimitPct for > reactiveHyst_pct window	Disconnect or degrade to reactive limit setpoint
TRIP-07	DC Over-Voltage / Anomaly	DC Volts > dcOV_TripV or sensor inconsistency	Disconnect; require field inspection

Important SCADA & Settlement Field Names

Field Name	Description
timestamp_utc	Unified 5-minute timestamp in UTC for all telemetry.
actual_mw	Measured inverter AC output (MW).
baseline_mw	30-day weather-normalized baseline expected production.
qualityFlag	Telemetry validity: 0=Good, 1=Suspect, 2=Bad
firmware_version	Inverter firmware string (e.g., v3.14.2)
serial	Unique inverter serial identifier (e.g., XG440-10245)
trip_code	Latest protective trip code (TRIP-31 etc.)

diag_bundle_url	Link to zipped diagnostics bundle for the device

Procedure: Emergency Firmware Rollback (Summary)

1. Verify rollback authorization from leadership (ticket approval CT-APPROVE-EMERG).
2. Validate current serial list and exclude hardware rev exceptions. Export list to CSV.
3. Create CMMS WO batch using WO-FW-ROLL-EMERG template for each site with fields: serialRange, plannedStartUTC, crewAssigned.
4. Backup DIAG bundle: pull DIAG-FRT-LOG and DIAG-OV-HYST before rollback. Store in diagnostics repository under path /diag/rollback/YYYYMMDD/.
5. Execute rollback using vendor CLI or OTA rollback; monitor for reconnection and 24-hour stability window.
6. If rollback fails (no reconnect or repeated trips), escalate to vendor P1 and schedule field visit.

Procedure: Settlement Dispute Preparation

1. Aggregate interval-level evidence: SCADA actual_mw, baseline_mw, qualityFlag, and telemetry snapshots.
2. Map scheduled positions for each asset and interval (DASETTLE or contract schedules).
3. Prepare reconciliation workbook showing DeltaMW and ImbalanceCharge per interval, with column for confidence and notes.
4. Submit dispute to ERCOT per settlement dispute window (usually within 14 calendar days); attach evidence bundle and contact points.

Contact & Escalation List (Sample)

Role	Name / Group	Contact	Escalation Hours
Vendor Firmware Lead	XG-Controls	fw-lead@xg-controls.example | +1-555-0100	24/7
Vendor Field Support	XG-Controls Field	field-support@xg-controls.example | +1-555-0110	Business Hours
O&M On-Call	Operations	om-oncall@company.example | +1-555-0200	24/7
Settlement Lead	Market Ops	settlement@company.example | +1-555-0300	Business Hours

End of appendix. All procedural artifacts should be versioned in the knowledge repository. Document model ID: VFIP-GD-EXEC-COMMS-2025.

Prepared by: Asset Performance & O&M Incident Response Team. Document created: 2025-12-10. Distribution: CIO, Head of O&M, Head of Market Operations, Vendor XG-Controls. For internal use only; contains synthetic incident artifacts for RAG testing.