



ELLIS & WATTS INTERNATIONAL, INC
4400 GLEN WILLOW LAKE LANE BATAVIA, OH 45103
(513) 752-9000

10/10/01 SB-010A
(Revised 12/31/01)

SERVICE BULLETIN

Start up Issue

This issue applies to the units indicated by (X):

☐ US only
☒ Foreign only
☐ Universally

The purpose of this bulletin is to address an important service issue relative to chiller start up:

- The **LC20MT/O** model chillers in **serial number range from 18067 to 18075** must be converted when started up in a 50Hz environment. For 380V/50Hz applications, please follow these instructions, in addition to switching SW6:

- 1) Locate electric box on condensing unit and remove front panel.
- 2) Locate transformer and move wire from H6 to H5 as shown on the instructions for the transformer for 380V application.
- 3) Replace panel on condensing unit.

For **serial number range from 18076 to 18087** in 380V/50Hz applications, please follow these instructions, in addition to switching SW6:

- 1) Locate electric box on condensing unit and remove front panel.
- 2) Locate transformer and move wire from H1 to H6 and move wire from H6 to H1 as shown on the instructions for the transformer for 380V application.
- 3) Verify the wires through to the switch.
- 4) Replace panel on condensing unit.

- The **LC10MT/O** model chillers have a globe valve located on the coolant supply line behind the right side connection panel for flow adjustment. The valve has been set for 60 Hz operation. For 50 Hz operation, the valve should be opened 100% to obtain the flow shown in following table:

Equipment	Coolant Flow	Coolant Temperature
TGWC	6.0 GPM +/- 10%	20° +/- 1C