

FCT SERVICE NOTE SN05083009a

Class A Service information enclosed.

Date: August 30, 2005

Subject: Fuse holder cap failure is occurring on some H16 MDAS fuse box assemblies, (Fuse Box P/N 2331963).

Effectivity: Lightspeed CT Systems with MDAS.

Details:

The adhesive holding the plastic cap to the fuse holder may fail. This causes the plastic cap to fall off exposing the top of the fuse chamber. This creates a potential 120V electrical shock hazard to Service personnel due to its proximity to the power switch on the fuse box.



Resolution:

The recommended corrective action is as follows, upon failure:

1. Order a new fuse holder, GE P/N 46-170042P26.
2. Order a replacement Fuse, GE P/N 46-170021P81, as this is critical to the corrective action.
3. Remove 120 VAC power from the fuse box assembly.
4. Remove the existing fuse and the defective metal top of fuse chamber.
5. Replace the 20A fuse on the “failed” fuse holder with GE P/N 46-170021P81.

6. Replace the top of the fuse chamber, with the top of the fuse holder from GE P/N 46-170042P26. It is not necessary to replace the entire Fuse holder. Use the cap of the replacement fuse holder to replace the “failed” fuse holder cap.
7. Discard the lower part of the fuse holder, GE P/N 46-170042P26. It is not used in the repair.

Douglas Hofstetter
FCT Service Engineering