

GE Healthcare Functional CT (FCT) Class C eService Notes are copyright (c) to General Electric Company Inc with all rights reserved. Class C eService Notes issued by GE Healthcare are proprietary to GE Healthcare Systems. Disclosure to persons not employed by GE Healthcare or not in possession of a Advanced Service Agreement with GE Healthcare is prohibited.

Duplication and distribution of any class of FCT eService Notes, in any form by entities other than GE Healthcare is strictly prohibited.

FCT SERVICE NOTE

06081808a

Class C information is Property of GE.

Date: August 18, 2006

Subject: DAS Tool Patch for 06MW03.4 VCT32 system

Effectivity: VCT32 slice systems with software version 06MW03.4

Issue:

The following tests in DAS Tool may fail if the detector has bad cell.

- DC Noise & DC Offsets test
- Offset Drift test

Cause:

Wrong scan protocols are being used in the above tests.

In these tests, VCT32 system is supposed to take 32 x 0.625mm and 32 x 1.25mm scans.

But it was found that 32 x 1.25mm scan actually collects 32 x 0.625mm scan data.

If there is any bad cell in the detector, the DAS tool would report error because the bad cell mapping data for 32 x 1.25mm scan does not match with the DAS Tool's 32 x 1.25mm scan data.

Solution:

Patch software was released to resolve this issue.

For the IB systems, download the patch ISO file from the CT Support Central below. Burn the CD and install to the system according to the instruction.

http://supportcentral.ge.com/bookupload/sup_book_default.asp?prod_id=15768&trng_doc_id=281360&vendor_flag=11&doc_cat_id=115255

(Go to LightSpeed 7.x (VCT64, VCT32) -> LightSpeed VCT32 -> VCT32 DAS Tool Patch for 06MW03.4)

For forward production, this patch software will be installed and shipped with system from FW34 shipments.

This problem will be fixed with the next software release (Jarrell software).

Takashi Uehara,
Lead Service Integrator VCT 32

Appendix Patch Install/Un-install Procedure

Install patch

- 1) Insert patch CD in DVD drive of the Host computer and open a Unix Shell. (with apps. down)
- 2) Type: **su - root** (passwd: #bigguy)
- 3) Type: **mount /mnt/cdrom**
- 4) Type: **patch_install -c**
- 5) Eject and remove patch CD from the Host computer. (Type: **eject** to eject CD)
- 6) Verify patch is installed:
 - a) [root@bayXX]# **rpm -qa|grep -i patch**
Confirm "**DAS_TOOL_PATCH-1-1**" is in the patch list.
 - b) Check protocols are correctly patched as follows:
Type: **md5sum /usr/g/protocols/service/v1.1/prot.das_drift_vdas_32slice.scanr**
Then confirm the following output is displayed:
a71a04fdc2801a2799eb0567ab9ea548 prot.das_drift_vdas_32slice.scanr

Type:
md5sum /usr/g/protocols/service/v1.1/ prot.das_dcnoise_offsets_vdas_32slice.scanr
Then confirm the following output is displayed:
9898edd81b87fb0a8277440538b088d7 prot.das_dcnoise_offsets_vdas_32slice.scanr

Un-Install patch

- 1) Open a Unix Shell. (with apps. down)
- 2) Type: **su - root** (passwd: #bigguy)
- 3) Type: **patch_install -u**
- 4) Verify patch is un-installed:
 - a) [root@bayXX]# **rpm -qa|grep -i patch**
Confirm "**DAS_TOOL_PATCH-1-1**" is not in the patch list.
 - b) Check protocols are returned to the original as follows:
Type: **md5sum /usr/g/protocols/service/v1.1/prot.das_drift_vdas_32slice.scanr**
Then confirm the following output is displayed:
bb55eb5d62595c1c597ef6b91e5ff7a9 prot.das_drift_vdas_32slice.scanr

Type:
md5sum /usr/g/protocols/service/v1.1/ prot.das_dcnoise_offsets_vdas_32slice.scanr
Then confirm the following output is displayed:
70e98720a53c33bbeaf11385443f76e4 prot.das_dcnoise_offsets_vdas_32slice.scanr