

GE Healthcare MI&CT Class C eService Notes are copyright (c) protected to General Electric Company Inc with all rights reserved. Class C eService Notes issued by GE Healthcare are proprietary to GE Healthcare Systems. Disclosure to persons not employed by GE Healthcare or not in possession of a Advanced Service Agreement with GE Healthcare is prohibited.
Duplication and distribution of any class of eService Notes, in any form by entities other than GE Healthcare is strictly prohibited.

MI&CT ESERVICE NOTE SN08010312a

Class C information is Property of GE.

This short-term informational note is invalid 6 months after the issue date.

Date: January 3, 2008

Subject: Erroneous Jarrell BIOS settings in Section 8.3 of LFC 07MW11.10

Effectivity: Any sites performing LFC 07MW11.10 for GOC3/GOC4

Details: Section 8.3 Step 3b is incorrect for Jarrell DARC BIOS Settings. Ignore step 3b completely. If a DARC BIOS pop-up appears for any Jarrell DARC2 Node, refer to the **Change DARC BIOS Boot Order - Restore Settings** link in Section 8.6 of the 07MW11.10 LFC. All Jarrell DARC Nodes should arrive ready to load from the vendor and should not require any DARC BIOS changes. Only Westville DARC and DARC2 Nodes require DARC Node BIOS to be enabled and then restored.

NOTE: Whenever DARC software load issues occur, place the SOL CD into the DARC Node and perform a power cycle or reset (as required) on the DARC Node. The SOL process takes 1-2 minutes and may correct load issue. The SOL CD should automatically eject and the DARC Node will reboot. If load issues continue and the DARC Node has LAN LED activity, connect a monitor and keyboard to the DARC Node to determine if the issue is reported by the DARC Node.

1. Revised Section 8.3 shown below:

8.3 Westville DARC Nodes Only: DARC BIOS Boot Order Enable Load

1. For DARC Node BIOS screen setup instructions for Westville ~~and Jarrell~~, refer to [Change DARC BIOS Boot Order - Enable Load](#).

NOTE: (For Jarrell DARC Nodes) refer to the link listed in Section 8.6 Restore DARC BIOS Settings, step 3 - [Change DARC BIOS Boot Order - Restore Settings](#)

2. **(For Westville DARC Nodes)** Verify that the **initial Boot device Priority** for OS load is set as shown below:

IBA 1.1.08 Slot 0338
ATAPI CD-ROM
Hard Drive
IBA 1.1.08 Slot 0339
Removable Devices

NOTE: The removable devices might not be present. This is OK.

~~(For Jarrell DARC Nodes) The Jarrell Boot device priority should be correct and should not need to be changed. Jarrell does not have an initial Boot device Priority; there is only one Boot Order setting. The process to check/set Jarrell boot device priority is not specifically documented, but the flow is the same as for Westville. If necessary (OS load fails), verify the Boot device Priority is set as follows:~~

GE Healthcare MI&CT Class C eService Notes are copyright (c) protected to General Electric Company Inc with all rights reserved. Class C eService Notes issued by GE Healthcare are proprietary to GE Healthcare Systems. Disclosure to persons not employed by GE Healthcare or not in possession of a Advanced Service Agreement with GE Healthcare is prohibited.

Duplication and distribution of any class of eService Notes, in any form by entities other than GE Healthcare is strictly prohibited.

~~IBA-GE slot 0320v~~

~~PM-ST048xxA (xx = 13, 15 or some value)~~

~~IBA-GE slot 0321v~~

~~PS-slimtype COMBO~~

~~EFI Boot Manager~~

~~**NOTE:** The EFI Boot Manager might not be present. This is OK.~~

Resolution:

1. Never change DARC BIOS for Jarrell DARC2 or VDARC Nodes unless instructed to check the BIOS and then utilize the **Change DARC BIOS Boot Order - Restore Settings** link.
2. Never change DARC BIOS for Westville VDARC Nodes unless instructed to check the BIOS and then utilize the **Change DARC BIOS Boot Order - Restore Settings** link.

Affected Service Publication:

- 07MW11.10 Load From Cold procedure already released:
LS 5.x Pro 16 Limited Access Service Info (Adv) for GOC3/GOC4 07MW11.10 LFC procedure

Potentially Affected Service Publications:

- 07MW11.10 LFC procedures
- 07BW08.3 and 07BW08.4 LFC procedures

PQR/SPR #:

Investigated this issue for Sourcing: Manufacturing DCAS Complaints and vendor DOA's directly attributed to incorrect Jarrell DARC Node BIOS setup per multiple procedures.

Resa Lambert

CT Operator Console Service Methods – Service Engineering