

[new...](#) | [new revision](#) | [page status](#) | [copy](#) | [move](#) | [delete](#)

welcome!
common documentation
library
ct tech pubs web page
ct water cooler
surveys
9800/hla
highspeed family (us)
ct/i
lightspeed family
all ct products
index
communiques pending
approval
customize
members

search:

advanced search
news: daily | weekly

go offline | chat | notify |
print | tutorial | help

home> all ct products

2302508 Brush Block Barrier Thickness

christopher hardiman (christopher c hardiman), 10/31/2002 - 05:00 pm

**Priority**

4 - Tips, Parts, Surveys, etc.

PROPRIETARY WARNING

This information is Property of GE - For GE Service Personnel Only.
Disclosure to third parties prohibited.

Communique Number

MQUE-5FFH8N

Equipment

HSA, CT/i, LightSpeed QXi

Problem

Barrier thickness on the S/A manufactured ETC replacement power brush block (2302508) is about double (.060") what it was on the ETC-manufactured equivalent brush blocks (.030") (2177224).

Corrective Action

A PCN has been issued to make the barriers as thin as they were on the ETC block. The thicker barriers will have enough clearance if placed carefully. Only about 3% of the some 400+ of these blocks have been returned as defective due to this problem. Stock will not be purged, so expect to see the thicker barriers for a time. The attached image shows the consequences of improper placement. Manually rotate the gantry to ensure proper clearances prior to running in the brushes.

You can download any of the files below by dragging them to your Windows desktop.
To open a file for reading, double-click it.

**Author**

Christopher C Hardiman

Revision

10/31/2002 05:00 PM

[new...](#) | [new revision](#) | [page status](#) | [copy](#) | [move](#) | [delete](#)

