

2244590 ERROR: HFA-PS OverCurrent Fault.

Indicates a problem with:

- HFA
- HFA Power Supply
- HFA Power Supply DC Output Cable

Extended Error:

Look at the fault LEDs on the front of the HFA-PS.

If the fault is **IPX OC**, **IPY OC**, or **IPZ OC**, this indicates an overcurrent on the primary windings of the supply transformers. The cause is usually the corresponding SGA/HFA or SGA/HFA Control Board, and often the power diodes in the Power Supply are damaged as a result.

Do not swap cables to isolate the damaged FRU.

Replace parts in the following order:

- 1) HFA Control Board (corresponding to the axis of failure)
- 2) HFA
- 3) Power Supply

If the fault is **ISX OC**, **ISY OC**, or **ISC OC**, this indicates an overcurrent on the secondary windings of the supply transformers. The cause could be the SGA/HFA, Power Supply, or DC Cables between the Power Supply and SGA/HFA. Use the following sequence to isolate the bad part:

- 1) Swap both DC cables between the failing axis and either of the other axes, *at the SGA/HFA*, and reproduce the problem. If the fault changes axes, replace the SGA/HFA.
- 2) Return the cables to normal at the SGA/HFA, and swap them at the Power Supply. If the fault changes axes, replace the DC cables. If it still remains on the original axis, replace the Power Supply.

(Note: If you do not see a red LED indicating an OverCurrent Fault, remove the JP1 jumper from the Power Supply Control Board. This will prevent the GP/GP3 from clearing faults on the Power Supply. You can use the Reset pushbutton on the front of the Control Board to manually clear faults.)

