

FCT SERVICE NOTE

SN05080610a

Class A Service information enclosed.

Date: August 5, 2005

Subject: VCT M3a LFC IP Address Conflict

Effectivity: VCT M3a

Details: NOTE: The VDARC subnet should not be changed during a software load.

The following procedure should be followed if your customer Ethernet backbone begins with 172.xxx.xxx.xxx

1. If hospital backbone starts with 172.xx.xx.xx and this is a first time install, continue and complete the software load on the HOST and VDARC. When the VDARC applications load is complete the VDARC subnet can be changed by running "reconfig".
2. If the hospital backbone starts with 172.xx.xx.xx, and the VDARC subnet was already changed, continue and complete the software load on the HOST and VDARC.
3. If the VDARC subnet was already changed and needs to be set to the 172.16.0 subnet continue and complete the load on HOST and VDARC and run reconfig to change the VDARC subnet.

Changing DARC subnet using the "reconfig" command

1. Open a Unix shell:
 - a. Type: **su - <ENTER>**
 - b. Type the root password: **#bigguy <ENTER>**
2. Type: **reconfig <ENTER>**
3. Click the **[Network]** button, check the **Advanced Options** box, then check the **Change DARC Subnet?** box and enter the following: **169.254.0.**
4. Click the **[Accept]** button.
5. When the system prompts you to reboot, click **[Yes]** to reboot the system.

Resolution: N/A

James Lehouillier
Console Service Methods Design Engineer