

FCT SERVICE NOTE

SN05111715a

Class A Service information enclosed.

Date: November 17, 2005

Subject: VCT FRDM Wizard Module Replacement utility

Effectivity: VCT systems

Details:

The FRDM Wizard for M3A has been found to have a problem when DASTools or Calibrations processes take longer than expected for the Minicheck and Calibration steps.

The problem is a timing issue in the software that can cause the FRDM Wizard to lockup.

Resolution:

The Dastools and Calibration issue is resolved in the M4 release of the VCT software. For M3A software, the FRDM wizard must still be run to make sure the detector configuration is updated properly. The DASTools and Calibrations steps can be run outside the utility.

M3A Process:

- Start the FRDM Wizard and replace the module.
- Select [Start Process] even if you already did so when starting the Wizard. The new module will be recognized by the Wizard and shown in the result screen. M4 software will have the change auto detected and reported.
- If no issues are noted, continue by selecting [Minicheck]. This will run the alignment scan. After reviewing the alignment data and closing the plot, the DASTools GUI will appear.
- Dismiss the Dastools screen and restart it from the Common Service Desktop.
- Run the maratio's and Autotest.
- Dismiss the Dastools interface and select [Prep for Calibrations] from the FRDM Wizard. This will open the Scanner Utilities screen.
- Dismiss the Scanner Utilities screen. The [Update Detector Configuration] button in the Wizard is now active.
- Perform the system calibrations outside the wizard.
- Perform IQ checks.
- Select the [Update Detector Configuration] to finish the process.

Steve Merritt
FCT Service Engineering