

FCT SERVICE NOTE

SN06011607a

Class A Service information enclosed.

Date: January 16, 2006

Subject: VCT 48V Power Supply reset

Effectivity: All VCT systems (7.x systems)

Details:

VCT 48V 1kW (Gantry stationary side) power supply may have zero output voltage. Cycling power to 120V does not fix it. Removing the common fan controller connection and cycling power does not fix it.

Resolution:

The 48V 1kW power supply is not designed to have 120V power cycled to it very fast. A hospital power outage for less than 1 minute may result in the 48V supply not powering back up properly. When servicing the unit, do not cycle 120V power quickly from the service switch board. This may damage the power supply. Allow the capacitance to drain from the unit by waiting at least 1 minute (not just the typical 10 second count). Customer may have to shut off CT power for at least 1 minute if a quick power outage occurs. System will need to properly reset. Vendor also indicates that the inrush resistors may burn out if power cycling is frequent in a short period of time. If the resistors burn out, the power supply 1 minute cycle will not fix issue. Power supply must then be replaced.

Shawn Ray
FCT Engineering