

FCT SERVICE NOTE SN07060412A

**Class M information is Property of GE - For GE Service Personnel Only.
Disclosure to Third Parties Prohibited.**

Date: June 4, 2007

Subject: Software download functionality for 07MW18.x and 07MW11.x

Effectivity: All CT Systems Loading 07MW18.x (VCT) and 07MW11.x (Non-VCT)

Details:

The stated software releases have an error in file permissions for 3 files required by the software download utility. These 3 files if not already existing are created by a ProDiags task but are created with "root" ownership that causes errors for software download. The initial FMI's for each of these software releases, (FMI 25389 for non-VCT & FMI 25394 for VCT) have the workaround for this issue included. This Service note is intended to provide a reminder that you should keep with the software set for any future LFC with these releases.

Once these files exist, the issue in the ProDiags software will not cause any further issues.

Resolution:

To enable usage of Update Management buttons in Service Desktop/Utilities, the ownership of three files listed below must be set at this time as ctuser. This is required after any LFC for 07MW18.x (VCT) or 07MW11.x (non-VCT) releases.

File Creation for ctuser:

1. Open a new unix shell and verify that you are ctuser (not as root). Type **whoami** and look for ctuser as the response.
2. Type **touch /tmp/cl** <Enter> (note: this is lower case L as the second letter)
3. Type **touch /tmp/cl1** <Enter>
4. Type **touch /tmp/cl2** <Enter>
5. To verify that ownership for cl, cl1, cl2 is now ctuser!
Type **cd /tmp** <Enter>
Type **ls -al cl*** <Enter>

Output should look similar to below, note the ownership for the "cl" files is ctuser.

Note: If files at any time exhibit "root" as the owner, see section below titled "Fix for files owned by root"

```
-rw-rw-rw- 1 ctuser users 9 May 31 11:38 cl
-rw-rw-rw- 1 ctuser users 2 May 31 11:38 cl1
-rw-rw-rw- 1 ctuser users 27 May 31 11:38 cl2
-rw-rw-rw- 1 insite root 70 Jun 4 10:20 clientdrv.trace
```

6. Close unix shell. Process is complete.

Fix for files owned by root:

NOTE: If these three files are not created by the steps provided here, then they will be created by the ProDiags task with wrong ownership and Software Download / InSite Update will not execute when run manually via CSD --> Utility --> Update Management. The system will respond with an error message -- request denied due to file ownership.

The output of the "ls" command above will respond with each of the "cl" files shown with root ownership as shown in the example below instead of ctuser.

-rw-rw-rw- 1 root root 9 May 31 11:38 cl

If files have been incorrectly created to have "root" ownership, type the following to delete them:

1. Open unix shell and switch user to root:
2. Type **su - root** <Enter> (must be root to delete root owned files)
3. Enter root password.
4. Type **rm /tmp/cl** <Enter> (note: this is lower case L as the second letter)
5. Type **rm /tmp/cl1** <Enter>
6. Type **rm /tmp/cl2** <Enter>
7. Close the Unix shell.

To correctly create these files with correct ownership, perform the steps in the section "**File Creation for ctuser**".

Keep this service note with the software disk set as a reminder for any future LFC with this software set. Future software releases will have this issue resolved.

Kevin Swain
Lead Service Integrator