

**MI&CT ESERVICE NOTE
SN07091412a**

Class C information is Property of GE.

This short-term informational note is invalid 6 months after the issue date.

Date: September 9, 2007

Subject: Service Pack 1.5 patch_install not mounting device.
Cannot install Service Pack 1.5 or any media using the /dev path with 6.2.9 OS

Effectivity: Any sites installed with CTT Operating System 6.2.9 using CT Service Pack 1.5

Details:

This is reported as a 6.2.9 OS issue (start_udev).

Discussions by Engineering on this issue:

Subject: /dev/cdrom problem

An intermittent problem with udev exists with OS 6.2.9. The installation of the OS, Apps and class C/M are OK but patch_install didn't work at all or did not work until a reboot.

This means fstab-sync and haldaemon ran properly and created the correct entries in /etc/fstab, correct directories in /media and correct links in /mnt (otherwise install.classC/M wouldn't have worked).

The start_udev is run twice (during rc.sysinit prior to service startup and at the end of service startup with rc.local). The start_udev creates a number of the /dev nodes, including cdrom links.

The second start_udev may be messing up the /dev/cdrom link.

The CTT Group explains that there can be a race condition between the internal IDE optical drive and the external "SCSI" optical being detected (and linked) first. This can also occur with multiple IDE optical drives (future MR).

In the interim, if patch_install fails, the user can run start_udev as root on the Host Computer, wait about 15 seconds (udev takes about this long to run even though command line returns OK almost immediately) and retry patch_install.

Solution:

Service Pack 2.0: The future solution is to update Service Pack patch_install to mount /mnt/cdrom and if it fails, try /mnt/cdrom1. Do not use /dev path.

Resolution:

1. Open a Unix Shell
2. Verify Application software is down. If Application software is not down perform the following script.
{ctuser@hostname} **cleanMon**
Wait approximately 1-2 minutes for Application software to go down
3. Become root:
{ctuser@hostname} **su -**
Password: **#bigguy**
[root@hostname ~]#
4. As root on the Host type:
[root@hostname ~]# **start_udev**
5. Wait at least 15 seconds after the OK.
6. Retry the Service Pack installation command.
7. If the Service Pack installation command fails, retry the start_udev command (wait 15 seconds after the OK) and the Service Pack installation command several more times.

Duplication and distribution of any class of eService Notes, in any form by entities other than GE Healthcare is strictly prohibited.

Note: Global CT Teams have reported success with the start_udev command.

8. If the retry of the previous commands continues to fail after several attempts, perform a reboot as root (stop Apps from auto-starting, if necessary). Retry the Service Pack installation command. If it fails, retry the start_udev command (wait 15 seconds after the OK) and the Service Pack installation command. Continue to retry the commands as required until the Service Pack is successfully loaded. Write an itrack if a reboot was required to load the Service Pack.

```
[root@hostname ~]# reboot
[root@hostname ~]# start_udev
```

9. After the Service Pack is successfully installed, a reboot is required.
[root@hostname ~]# reboot

Affected Service Publication:

All LFC procedures utilizing the 6.2.9 OS with CT Service Pack 1.5:

- **07MW11.10**
 - 5193891-800 - LS 5.X Pro16 Limited Access Service Info (Adv), Rev 2
07MW11.x SW LFC (GOC3/GOC4)
 - 5224328-800 - LS 5.X (HP60) Limited Access Service Methods (Advanced), Rev 2
07MW11.x SW LFC (GOC3/GOC4)
 - 5133451-800 - LS 5.X (HP60) Service Methods (Advanced), Rev 9
07MW11.x SW LFC (GOC3/GOC4)
 - 5193755-800 - BrightSpeed (Ltd. Access) Service Methods Adv, Rev 4
07MWxx.x PF_SW LFC (GOC3/GOC4)
- **07MW18.4**
 - 5193575-800 - LS 7.X Limited Access Service Info (Adv), Rev 2
07MW18.x SW LFC (LS7.X)
- **07BW08.3 and 07BW08.4.**
 - 5196839 - LS RT16 and Xtra Ltd Access Service Info (Adv), Rev 3
07BW08.x LFC Procedure (LCGOC/GOC4)
 - 5181166-800 - BrightSpeed Select Service Methods Adv, Rev 2
07BW08.x LFC Procedure (GOC3/GOC4)

PQR/SPR #:

- FCTge30938 Link of /dev/cdrom was invalid --- for sp3-ss
- FCTge30940 Link of /dev/cdrom was invalid --- for pfsp-ss

Resa Lambert

CT Operator Console Service Methods – Service Engineering

MI&CT Engineering Manager Reviewer: _____ Mark Nyman _____