

[new...](#) | [page status](#) | [copy](#) | [move](#) | [delete](#)


welcome!
 ct tech pubs web page
 ct water cooler
 ct tech pubs updates
 surveys
 9800/hla
 highspeed family (us)
 ct/i
 lightspeed family
 yms family
 all ct products
[index](#)
 old ct emails
 communiques pending
 approval
 communique change
 requests
 customize
 members

search:
 

advanced search
 news: daily | weekly

go offline | chat | notify |
 print | tutorial | help

home> index

Reconfig Replaces Characterization Files with Defaults

christopher hardiman (christopher c hardiman), 10/04/2002 - 02:58 pm

**Priority**

1 - Big Issue, Be Sure to Read

PROPRIETARY WARNING

This information is Property of GE - For GE Service Personnel Only.
 Disclosure to third parties prohibited.

Communique Number

MQUE-5EKH6S

Equipment

LightSpeed Plus, Ultra, & 16

Problem

It was recently discovered that use of reconfig, regardless of database reset selections, will delete current mechanical characterization files for tilt, elevation, and cradle longitudinal. These files are replaced with default values. Based on how systems are installed and reconfig is used to alter network and camera configurations, it is likely that many Plus, Ultra and 16 systems will be using default values. Since the default values are set with huge margins of safety, this will result in, for example, not being able to lower the table as far as expected without error. Gantry displayed values will also not be in keeping with actual physical system positions.

Solution

At each potentially effected site, execute the following command in a Unix Shell: NOTE - 3 DOTS DENOTES ONE SPACE IN THE COMMAND
 BELOW - REPLACE THE 3 DOTS WITH ONE SPACE
 diff.../usr/g/fw/char/tilt.def.../usr/g/fw/char/tilt.char If the prompt returns and no values are displayed, the system is running under the default characterization files and it is necessary to perform tilt, elevation and cradle characterizations. After performing characterization or obtaining a numeric value using the diff command, take a blank MOD and, utilizing the Save System State function, save the characterization files to it. Each time characterization is performed update this MOD. After each execution of reconfig, restore characterizations from this MOD. This will also effect the installation procedure. Be sure to restore mechanical characterization every time reconfig is run. This bug will be fixed in LS2002 software release due November 2002. Note that it is likely that these defaultt characterizations were saved to the state MOD during installation. If a restore of these is attempted, execute the diff command to ensure that the defaults are no longer being used.

Author

Christopher C Hardiman

Revision

10/04/2002 02:58 PM

[new...](#) | [page status](#) | [copy](#) | [move](#) | [delete](#)

