

FCT SERVICE NOTE

SN06101213a

Class A Service information enclosed.

Date: October 12, 2006

Subject: FRDM Wizard fails to run

Effectivity: All VCT systems

Details:

You may see the following error when replacing a VCT detector module after the "Start Process" button is selected from the FRDM Wizard:

Could not open or parse reference file.

Error occurred while extracting ChangeDetLog

This is due to a missing detector config file that should have been on the system when delivered and restored with every Restore State.

The missing file will prevent Minicheck from launching in the FRDM Wizard.

Resolution:

From a Unix shell, must be ctuser, type the following command (capital M and DCF only):

createMasterDCF

This will re-initialize the detector configuration file. Restart the FRDM Wizard and you will be able to continue through the steps.

A software design change is in process to auto correct this issue for a future software release.

Steve Merritt
FCT Service Engineering