

FCT SERVICE NOTE

SN 07012909A

Class M information is Property of GE - For GE Service Personnel Only. Disclosure to Third Parties Prohibited.

Date: January 29, 2007

Subject: VCT HALO HDAS64 FRDM Wizard bug

Effectivity: VCT HDAS (HALO detector) systems only

Details:

A last minute bug introduced into 06MW29.7 right before release has recently been identified in the 06MW29.7 software release that causes a hang in the FRDM Wizard when replacing a detector module. This bug causes the utility to hang when the MiniCheck step is started. The utility will indicate reading HART data but will not continue. Reading HART data (onboard module data) typically should take less than 1 minute.

This issue does not affect VDAS64 (Sherlock detector) configurations.

Resolution:

An emergency patch for this issue and some other issues is currently in process of being verified and validated for release to all systems running 06MW29.7. This patch includes a fix for the HDAS (HALO) based FRDM Wizard bug.

Until this patch is deployed any HDAS (HALO) detector module replacement will require a Unix shell script command to be run after replacing the module and before running the FRDM Wizard steps.

Open a Unix shell and type the following command from a ctuser prompt:

createMasterDCF (NOTE: pay attention to capital characters)

Send an email to **Merritt, Steve (GE Healthcare)** after this script has been run with the system ID and typical site operation hours. I will need to remotely log into the site to manually update the HART data at some point after the repair as running the above script causes the system to not automatically update the onboard HART data. There are two fields in the module HART data that need to be updated for continued service software operation for future module replacements but does not affect Customer operation or troubleshooting.

This service note will no longer apply after the upcoming 06MW29.7 patch has been installed. This service note will be updated to indicate the patch identification details as soon as they are known.

Steve Merritt
FCT Service Engineering