

TECHNICAL BULLETIN



MODEL/DERIVATIVE:
All Models

Bull. N°: **0022**
CDS. ref: **R4083bu**
Issue: **1**
Date: **21.02.96**

AFFECTED RANGE:
All versions

PROBLEM:
INADVERTENT OPERATION OR MALFUNCTION OF AIRBAG

Allegations (not particularly in respect of Rover Cars) of possible inadvertent operation or malfunction of air bag due to installation of electrical equipment such as car / mobile telephones.

CAUSE:
See below.

ACTION:
All Rover cars are tested for immunity to 'Radio Frequency Fields'. Under normal operating conditions we would not therefore expect the fields produced by car/mobile telephones to exceed the levels simulated in our testing. It is possible however, that the fitting of such items as power boosters could cause localised effects which result in higher field strengths than those used in testing and Rover cannot therefore guarantee immunity.
A more likely cause of inadvertent operation of an air bag would be splicing into the yellow coloured air bag harness to provide a feed or earth for electrical accessories.
Power feeds and earths for such items as car/mobile telephones must always be taken direct from the battery and incorporate their own fuses.

PARTS INFORMATION:
Not Applicable

WARRANTY CLAIMS:
Not Applicable