

DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
16/08/2026	10/08/2026	☑	GK CONTRACTING W.L.L	DIRECT SALES - SEHLA	Contractor	1OOC422042	Product	PRODUCTION	SITRA	8" PLAIN & 8" SANDWICH	VERY WEAK & NOT INCOHERENT		The customer complained that a few blocks were received with cracks. The issue was related to the initial stage of production when the machine was starting up. After production started the machine settings were adjusted and the issue was corrected. The labour should have inspected the blocks coming out of the machine and removed any blocks with visible cracks before they were sent for delivery. The customer has already used the blocks.	Resolved - Positive	SATISFIED		NOT TRACKED

[illegible]

08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	100C412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED	
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED	

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	✓	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanial have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	---	-------------------------------	----------------	------------	------------	---------	------------	--------	-----------------	--------	--	---------------------	-----------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	---	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	✓	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	---	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	---	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	✓	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	---	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	---	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	✓	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanial have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	---	-------------------------------	----------------	------------	------------	---------	------------	--------	-----------------	--------	--	---------------------	-----------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	✓	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanial have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	---	-------------------------------	----------------	------------	------------	---------	------------	--------	-----------------	--------	--	---------------------	-----------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	---	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------	----------------	------------	------------	---------	------------	--------	-----------------	--------	--	---------------------	-----------------------	---	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------	----------------	------------	------------	---------	------------	--------	-----------------	--------	--	---------------------	-----------------------	---	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	---	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	✓	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	---	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	---	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------	----------------	------------	------------	---------	------------	--------	-----------------	--------	--	---------------------	-----------------------	---	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------	----------------	------------	------------	---------	------------	--------	-----------------	--------	---	---------------------	-----------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------	----------------	------------	------------	---------	------------	--------	-----------------	--------	--	---------------------	-----------------------	---	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------	----------------	------------	------------	---------	------------	--------	-----------------	--------	--	---------------------	-----------------------	---	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------	----------------	------------	------------	---------	------------	--------	-----------------	--------	--	---------------------	-----------------------	---	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	✓	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlai have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	---	-------------------------------	----------------	------------	------------	---------	------------	--------	-----------------	--------	--	---------------------	-----------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	✓	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanial have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	---	-------------------------------	----------------	------------	------------	---------	------------	--------	-----------------	--------	--	---------------------	-----------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	✓	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	---	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	---	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	---	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	✓	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	---	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	---	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------	----------------	------------	------------	---------	------------	--------	-----------------	--------	--	---------------------	-----------------------	---	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✔	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✔	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✔	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✔	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✔	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanalal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------	----------------	------------	------------	---------	------------	--------	-----------------	--------	---	---------------------	-----------------------	---	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	✓	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlai have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	---	-------------------------------	----------------	------------	------------	---------	------------	--------	-----------------	--------	--	---------------------	-----------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	✓	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	---	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	---	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix							
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)	
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED	
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED	
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED	
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED	

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	✓	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	---	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	---	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------	----------------	------------	------------	---------	------------	--------	-----------------	--------	--	---------------------	-----------------------	---	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	✓	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	---	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	---	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	✓	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	---	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	---	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	✓	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	---	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	---	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------	----------------	------------	------------	---------	------------	--------	-----------------	--------	--	---------------------	-----------------------	---	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanalal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------	----------------	------------	------------	---------	------------	--------	-----------------	--------	---	---------------------	-----------------------	---	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------	----------------	------------	------------	---------	------------	--------	-----------------	--------	--	---------------------	-----------------------	---	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	✓	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	---	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	---	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	✓	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	---	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	---	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	✓	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix						
DATE OF COMPLAINT	DATE OF ISSUE	COMPLAINT CLOSED?	CUSTOMER NAME	SALESMAN	CUSTOMER TYPE	ORDER No.	ISSUE TYPE	DEPARTMENT	SITE	AFFECTED PRODUCT	SALES NOTES	DEPARTMENT 'S NOTES	QC NOTES	CURRENT STATUS	CUSTOMER OUTCOME	STEPS TAKEN BY QC DEPARTMENT TO REDUCE REPEAT OF ISSUE (INTERNAL OR EXTERNAL)	DATE OF COMPLAINT CLOSED (QC ONLY)
02/04/2026	01/04/2026	✓	JEHAN ABDULMAJEED HASAN ABDULLA	JAFFAR AL-TAAN	Contractor	1OOR171943	Product	PRODUCTION	DEYAR AL-MUHARREQ	8" LINED BLOCKS	Cracks		Site has been visited and we found 19 blocks with crack the customer asked to return the blocks This happen coz of the cuber attender didnt remove the rejected clocks and it has been supplied to the customer	Resolved - Positive	She is satisfied now..	We have informed the cuber attender to double check.	NOT TRACKED
06/04/2026	27/01/2026	✓	BANI JAMRAH CHARITY SOCIETY	JAFFAR AL-TAAN	Contractor	1OOC407750	Product	PRODUCTION	BANI JAMRAH	80mm Grey (Grade 2).	Different size in interlock		Site has been visited, and the customer was taking second-quality materials at a special price. That is why there was a difference from batch to batch. I convinced the customer to mix and use the materials, and he agreed. After that, he requested an extra 100 m. I informed him that this would not match the existing line, and he agreed to proceed with the supply and use.	Resolved - Positive	He is satisfied now..	there are no steps.	NOT TRACKED
08/04/2026	30/03/2026	✓	QASSIM ALI	DIRECT SALES-KHAMIS	Contractor	1OOC412114	Product	PRODUCTION	SITRA	DOUBLE WASHED SAND	Too much dust in D.W. sand		The site was visited, and the customer reported that shell smaller than 2 mm were present in the sand, which was causing cracks in the plaster work. Action taken: 5 ton were replaced with new sand	Resolved - Positive	He is satisfied now..	Plaster sand has been received from other suppliers.	NOT TRACKED
21/04/2026	16/04/2026	✓	TOP JUSOOR	NIYAS	Contractor		Product	PRODUCTION	QURAYAH	35N OPC	Receiving 100mm slump Only.		Our technician was present at site, and the slump was checked and accepted by the clinet as per the customer request (120 mm). This slump is requires proper vibration to ensure good compaction. The honeycombing observed is mainly due to insufficient vibration during casting, not the concrete itself.	Resolved - Positive	He is satisfied now..	He should take steps from his side.	NOT TRACKED

28/04/2026	25/04/2026	☒	HUSSAIN AHMED JAFFAR ALORAIBI	JAFFAR AL-TAAN	Contractor	10OR172855	Product	PRODUCTION	TOOBLI	8" WHITE BLOCKS	Cracks	Customer Name: Husain Ahmed Location: Toobli Product: 8" White Block 600 pcs Site has been visited and the customer mentioned that some blocks were cracked and damaged. After checking the damage happened during loading and unloading. Around 42 blocks are damaged. The customer is requesting to replace the blocks with sandwich block	Resolved - Positive	He is satisfied now..	Rgarding white block Issue Summary My self ,Mr Hussan Nokhtha, Mr sajit AND Mr Mohanlal have identified that the current lifting method is causing structural failure in the white blocks. The blocks have a compressive strength of only 2 N, making them a highly sensitive product that requires specialized handling. Root Cause Analysis Comparison: The "Kingdom" crane lifts the blocks by securing the wooden pallets they sit on. Current Failure: Our crane uses a clamping mechanism directly on the blocks. Impact: The pressure exerted by the clamps exceeds the 2 N strength limit, resulting in immediate damage to the product. Proposed Solutions To prevent further damage, we must treat these as a "Special Product" and implement one of the following lifting methods: Lifting Belts: Use specialized lifting belts positioned underneath the wooden pallet to hoist the entire unit. Pallet-Based Clamping: Adjust the crane attachment to clamp the wooden pallet itself rather than applying pressure to the blocks.	NOT TRACKED
------------	------------	-------------------------------------	-------------------------------------	----------------	------------	------------	---------	------------	--------	--------------------	--------	--	------------------------	--------------------------	--	-------------

27/04/2026	27/04/2026	☒	TOP JSOOR	NIYAS	Contractor	1ORR078010	Product	PRODUCTION	JANABIYAH	45N SRC	Loose Mix				
------------	------------	-------------------------------------	-----------	-------	------------	------------	---------	------------	-----------	---------	-----------	--	--	--	--