

Oxide Tester PC – Replacement PC Setup

This guide provides step-by-step instructions to set up a replacement Oxide Tester PC. The replacement computer has been shipped with all required software pre-installed and authorized.

Record Existing Shunt Resistance

1. On the existing Oxide Tester computer, launch the Oxide Tester program.
2. Select the **Configure** button on the main screen.
3. Record the **Shunt Resistance** value (in ohms).

Replacement PC Setup Instructions

1. Power on the replacement PC and log in.
 - a. **Username:** User
 - b. **Password:** *(none)*
2. Connect the existing Oxide Tester junction box to the PC via USB.
3. Set up USB modules:
 - a. Launch the **Instacal** program (shortcut is on the Desktop).
 - b. If prompted to update the registry power settings, **allow** the update.
 - i. A reboot will be required. After rebooting, run **Instacal** again.
 - c. **Instacal** should automatically detect the USB modules.
 - i. Click **OK** to add them to the configuration file.
4. Configure USB-3102 Module:
 - a. From **Instacal** program, double-click the USB-3102 module.
 - b. Ensure board number is set to **#0**.
 - c. Set all four output channels to **0-20mA**.
 - d. Record the **serial number** of the board.
5. Configure USB-1608G Module:
 - a. From **Instacal** program, double-click the USB-1608G module.
 - b. Ensure board number is set to **#1**
 - c. Set input channel setting to **8 Differential Channels** (from dropdown)
 - d. Record the **serial number** of the board.
6. Close Instacal program
7. Set Shunt Resistance
 - a. Launch the Oxide Tester program.
 - b. Select **Configure** button on main screen.
 - c. Select the **Shunt Resistance** value to modify.
 - i. **Password:** 123
 - d. Enter the Shunt Resistance value recorded from the original PC.
 - e. Click **Save Changes** button.
8. Run a few oxide tests to verify that the system is functioning correctly.