Hylan Datacom & Electrical Contracting Daily Work Report

Customer :	Extenet Node Testing - Phase 3			_ Date: _	.08/29/2017		
Project :					Job #	446	
wo # : _				Truck #	338		
	0	Manpower In	formation			O.T.	
Name: _	Ser			Reg.:_		OT:_	3
Name: _	Ceraldi			Reg.:		OT:_	3
Name: _	Pagan			Reg.:		OT:_	3
Name: _						OT:_	
Name: _				-		OT:_	
Name: _				_		OT:_	
Name: _				_		OT:_	
Name: _				Reg.:_		OT:_	
-:		Description	Of Work	: :		=======================================	
Tester repor	rted to 54 Laight S	treet		:		=======================================	
Splicers reported to node 110 (LP 10623)							
Tester noted that RU #1 was in alarm but had traffic on fiber from node							
Splicers pulled fibers from node ports so fibers could be traced.							
Fiber #1 had high losses and numerous bad Vz patches was out of loss budget for span							
Fiber #2 also had bad Vz patches and was just under budget loss alowances							
Both fibers traced and node left unplugged four Vz to repair/test							
Splicers reported to node 85 (LP 11192) to address trouble ticket for this nice							
Splicers found fiber #1 in node box had severe macrobend and an open splice 225'							
from node. Fiber #2 was within budget. Splicers and tester traced fibers and left node							
patches disconnected for Vz to repair/test							
Tester repor	ted to 227 E30th S	Street					
Splicers reported to Node 174 (LP 10425) Splicers located node tail in base of pole							
and no node	e equipment up on	pole. Splicers ar	nd tester h	ad no con	tinuity a	nd splice	rs
reported live traffic on fiber #1 even though fiber #1 were both unplugged at hub							
Tester found	d fibers 1&2 at hub	only trace 700' i	from equip	ment. Spli	cers and	d tester b	oth
traced fibers	5.						
Splicers rep	orted to Node 167	(LP 11169) Test	er has NO	CIRCUIT I	eaving E	xtenet pa	anel
Splicers trac	ced fibers from no	de only.					
Splicers rep	orted to Node 161	(LP 10419)					
Tester reports node is operating correctly and node is working with no alarms showing							
Splicers disconnected node and tester and splicers traced fibers							
Node returned to operation with no alarms showing							