
DEV NUMBER:	ORIGINATOR: DATE:		ΓE:	RAIN BIRD BUSIN			SINESS UNIT (SBU and PLANT) W/ PRIM		MARY DESIGN CONTROL: SHEET:	
DEV25-0093	Abdul Cast	illo	12-Mar-25			025 O	TY	>>> GLF]	
DMR# (IF APPLICABLE): DEVIATION NEW ✓				DEVIATION FORM (DRAWING)					1 OF	
TYPE: EXTENSION ☐ OF DEV#:				FORM#233813-01 REV: T		AFFECTED MFG P	PLANTS (WHERE U	SED):	•	
TOP-LEVEL SKU P/N	(S) AND MODEL NUMBER(S):		EFFECTIVITY DATE:	EXPIRATION DATE:	005 LAM	013S STL 🔲	025 OTY 🗹	041 NOG 🔲		
	Golf: Housing riser 7	02,552,752	12-Mar-25	12-Jun-25	008 BUY 🗌	019 AZU 🔲	028 TUC	047 TUC		
PROJECT NAME OF	NO. (OPTIONAL):					013E EEX 🔲	020MX NMD	026 ELG 🗹	CHINA 🔲	
REASON FOR DEVI	ATION:							APPROVALS (ALL F	REQUIRED):	
Allow to run 213939 M1098 parts from QAP1001 with the following issues.									QUALITY MGR. OR QUALITY ENG.	
1. The date code is incorrect (it displays 24 instead of 25). 2. More than.015", actually.032".									Arturo Ramos / Beltran, Juan Beltran	
3. Burn marks on the exterior. (see picture below)									MANUFACTURING ENGINEER	
RISK ASSESSMENT/ CORRECTIVE ACTION PLAN (NAMES & DATES)/ COMMITMENT:									Guillermo Acosta/ Delfino Ramirez	
l ow: The PCO-30467	ran 80 motor assemblies with i	no problems on EEE 30 ro	tors were comple	eted with no problems on F	FFF and every rotor passed	the water tank with r	no leaks	PROD. ENG. MGR. (OR PLANT ENG. MGR	
Low: The PCO-30467 ran 80 motor assemblies with no problems on FFF, 30 rotors were completed with no problems on FFF, and every rotor passed the water tank with no leaks. El Lago Have 62K pcs from QAP, this covers 12WFC									Paul Dibene / Xavier Vela	
Action plan: 1 8 weeks of inventory to allow adjust or fabricate the component and evaluate again with another QAP1000. Resp. Belem Torres/ Jorge Rivero									BUYER OR BUYER/PLANNER	
1 0 weeks of inventory to allow adjust of labilitate the component and evaluate again with another QAF 1000. Nesp. Determ forces/ Jurge Nivero									Diana Rincon/ Belem Torres	
DRAWING NUMBE	R: DRAWING REVISION:	/ISION: DEVIATION REVISION: DRAWING TITLE/ PART DESCRIPTION: VENDOR:					PLANT MANAGER	PLANT MANAGER		
213939	A	A5	HOUSING RISER 702, 552, 7552			026 El Lago		Jorge	Jorge Borquez	
								SBU PRODUCT MGI	R. OR SBU ENG. MGF	
								Altan Tolan /	Javier Guardado	
								TOOLING ENGINEE	R (MOLDED PARTS ONLY)	
								Jorge Rivero	Cesar Rodriguez	
								OTHER:		
								Daniel Mendo	oza / Omar Curiel	
DESCRIPTION OF D	EVIATION (IS/WAS CONDITIC	ON AND DRAWING ZONE	FOR EACH PAF	RT NO. OR ATTACH REDI	LINE PRINTS):			QUALITY DIRECTOR BACK-TO-BA	R (REQUIRED FOR ACK DEVIATIONS)	
91	010	○ □	. MAXIMUM FLASH APPENDAGO	E TO BE .015 THICK X .030 HIGH				1		






C-M (8.) DATE CODE AS SHOWN, VERIFY CORRECT SETTING











Castillo, Abdul Ivan OTY 4332

Castillo, Abdul Ivan OTY 4332 From:

Sent: Wednesday, March 12, 2025 8:45 AM

To: Ramos, Arturo OTY2 4313; Beltran, Juan Martin LAG 4628; Acosta, Guillermo OTY 4319;

> Ramirez, Delfino ELAG 1202; Dibene, Paul OTY2 4687; Vela, Xavier OTY 4377; Rincon, Diana OTY 4341; Carrillo, Belem OTY 4376; Mendoza, Jorge Daniel ELAG 1245; Borguez, Jorge OTY 4398; Tolan, Altan SOPT 6553; Guardado, Javier OTY 4310; Rivero, Jorge

ELAG 4342; Rodriguez, Cesar Alberto NOG 5053; Curiel, Omar ELAG 1284

Subject: DEV25-0093 Allow to run 213939 M1098 parts from QAP1001 with incorrect date

code, Flash, burn marks

Attachments: DEV25-0093 213939 A riser 700 .pdf.xls

Recipient

Importance: High

Categories: ECO & DEV to do

Tracking: Ramos, Arturo OTY2 4313 Approve: 3/12/2025 10:59 AM

Mendoza, Jorge Daniel ELAG 1245 Read: 3/12/2025 9:44 AM

Read

Response

Approve: 3/12/2025 9:45 AM

Beltran, Juan Martin LAG 4628 Approve by O. Curiel Acosta, Guillermo OTY 4319 Approve: 3/12/2025 2:12 PM

Ramirez, Delfino ELAG 1202 Read: 3/12/2025 9:12 AM Approve: 3/12/2025 9:13 AM

Dibene, Paul OTY2 4687 Approve by X. Vela

Vela, Xavier OTY 4377 Approve: 3/12/2025 12:11 PM Rincon, Diana OTY 4341 Approve: 3/12/2025 9:45 AM

Carrillo, Belem OTY 4376 Read: 3/12/2025 8:45 AM Approve: 3/12/2025 8:45 AM

Borquez, Jorge OTY 4398 Approve: 3/12/2025 2:18 PM

Tolan, Altan SOPT 6553 Approve: 3/12/2025 9:02 AM

Guardado, Javier OTY 4310 Read: 3/12/2025 8:45 AM Approve by Email

Rivero, Jorge ELAG 4342 Approve by C. Rodriguez Approve: 3/12/2025 8:56 AM Rodriguez, Cesar Alberto NOG

5053

Curiel, Omar ELAG 1284 Read: 3/12/2025 2:18 PM Approve: 3/12/2025 2:18 PM

Hello everyone

Review and approve the attached DEV25-0093

Allow to run 213939 M1098 parts from QAP1001 with incorrect date code, Flash, burn marks

Let me know if you need more information, I'll be happy to provide it. 24-hour rule is invoked for indicated approvals

Greetings

Abdul I. Castillo

Sr. Product Engineer at Ensambles Hyson

Castillo, Abdul Ivan OTY 4332

From: Guardado, Javier OTY 4310

Sent: Wednesday, March 12, 2025 8:47 AM

To: Castillo, Abdul Ivan OTY 4332

Subject: Approve: DEV25-0093 Allow to run 213939 M1098 parts from QAP1001 with

incorrect date code, Flash, burn marks

Attachments: DEV25-0093 Allow to run 213939 M1098 parts from QAP1001 with incorrect date

code, Flash, burn marks

Hi Abdul,

I approve contingent the approval of Doug Busch.

Best, Javier

.____

Javier Guardado

Quality and Operations Mgr - Golf Office and Mobile: 619-661-4310

Ensambles Hyson

Ave. Industrial 333 Seccio Dorada, Mesa de Otay 22500 Tijuana, Mexico



Castillo, Abdul Ivan OTY 4332

From: Busch, Doug SOPT 6533

Sent: Wednesday, March 12, 2025 11:55 AM

To: Castillo, Abdul Ivan OTY 4332

Subject: RE: DEV25-0093 Allow to run 213939 M1098 parts from QAP1001 with incorrect

date code, Flash, burn marks

I approve.

Regards,

Doug

Douglas Busch, P.E.

Principal Engineer 520-741-6533

Rain Bird Corporation

6991 East Southpoint Road Tucson, Arizona 85756 RainBird.com

From: Castillo, Abdul Ivan OTY 4332 < AbCastillo@rainbird.com>

Sent: Wednesday, March 12, 2025 10:46 AM

To: Busch, Doug SOPT 6533 < DBusch@rainbird.com>

Subject: FW: DEV25-0093 Allow to run 213939 M1098 parts from QAP1001 with incorrect date code, Flash, burn marks

Importance: High

Doug

I miss you on the original email chain, please approve deviation.

Regards

Abdul I. Castillo

Sr. Product Engineer at Ensambles Hyson

US Phone: 619-661-4332 **MX Phone**: 664-973-4332

From: Castillo, Abdul Ivan OTY 4332

Sent: Wednesday, March 12, 2025 8:45 AM

To: Ramos, Arturo OTY2 4313 arramos@rainbird.com; Beltran, Juan Martin LAG 4628 jubeltran@rainbird.com; Ramirez, Delfino ELAG 1202 DRamirez@rainbird.com; Dibene, Paul OTY2 4687 PDibene@RainBird.com; Vela, Xavier OTY 4377 XVela@rainbird.com; Rincon, Diana OTY 4341 drincon@rainbird.com; Carrillo, Belem OTY 4376 becarrillo@rainbird.com; Mendoza, Jorge Daniel ELAG 1245 Jmendoza@RainBird.com; Borquez, Jorge OTY 4398 jborquez@rainbird.com; Rivero, Jorge ELAG 4342 JBuardado@RainBird.com; Rivero, Jorge ELAG 4342 JBuardado@RainBird.com; Rodriguez, Cesar Alberto NOG 5053 CeRodriguez@rainbird.com; Curiel, Omar ELAG 1284