

LEDGERWOOD REFRIGERATION SERVICES, INC.

Technician Field Note —not a work order

Technician: Y. Brill, Lic. #RT-40882

Site: Brightleaf Markets —Millbrook —Store 14

Date: September 22, 2020

On site under: WO-109331 (deli case A-1 thermostat —closed same visit)

Subject equipment: Rack B-3, CR-820, s/n CR820-13-4471, installed 2013

Why this note exists

No work order is open on Rack B-3. I gauged it on my own time because of the aisle 12 product complaints raised by the store in March. There is nowhere in the system to put this, so it is going to my service manager as a note.

Readings —Rack B-3

Measurement	Reading	Expected	Delta
Discharge temperature	218 °F	185–190 °F	+30 °F over
Suction pressure	11.2 psig	10–12 psig	normal
Discharge pressure	232 psig	215–225 psig	high
Superheat	9 °F	8–12 °F	normal
Compressor amp draw	41.3 A	38–40 A	slightly high
Oil level	3/8 sight glass	1/2	low-normal

Finding

Discharge temperature thirty degrees over with normal suction and normal superheat points at the discharge valve, not the charge and not the metering device. Valve plate is leaking on the discharge side and the compressor is reprocessing hot gas.

Recommendation

Schedule a valve plate replacement on B-3. It will hold as it is for a period but it will not hold indefinitely, and a discharge valve that fails outright will take the compressor with it.

This is the failure mode I would expect to produce exactly the intermittent overnight warming the store has been reporting: the rack recovers during the day when the load is light and loses ground on the overnight pull-down.

Not scheduled. No open order on this rack.

Y. Brill, September 22, 2020