

LEDGERWOOD REFRIGERATION SERVICES, INC.

Service Order

Order number	WO-114872
Customer	Brightleaf Markets
Site	Millbrook —Store 14
Agreement	SA-2019-4412
Opened	May 12, 2021, 08:17
First Reported	05/12/2021
Requested by	W. Achterberg, Director of Facilities
Assigned	Y. Brill
Attended	May 14, 2021
Equipment	Rack B-3, CR-820, s/n CR820-13-4471
Authorization	Diagnostic granted; repair over \$5,000 requires customer approval

Reported symptom (customer)

Intermittent product temperature excursions, soft product, elevated shrink.
Frozen food line, aisle 12, and backroom walk-in.

Diagnostic findings

Measurement	Reading	Expected	Delta
Discharge temperature	229 °F	185–190 °F	+41 °F over
Discharge pressure	248 psig	215–225 psig	high
Compressor amp draw	43.9 A	38–40 A	high
Valve plate, discharge side	scored, visible blow-by	—	failed

Valve plate wear is **not recent**. Scoring pattern and carbon deposition are consistent with extended operation in this condition.

Recommendation

Replace, do not repair. The CR-820 is a 2013 unit at the end of its economically serviceable life; valve plate availability for this model is lengthening and a valve replacement in a compressor with this hour count and this history buys twelve months at the outside.

See quote **Q-88041**.

Technician note

This rack was flagged internally on September 22, 2020 following gauging under WO-109331. The condition has worsened from +30 °F discharge to +41 °F in the intervening eight months.

Status at close of visit: diagnosed, quoted, awaiting customer authorization.