



NCR No: 11749

QER: JULIMAR DEVELOPMENT PHASE 3 SF301229C002.05+06+07 (ST203.72124)

- Zeta Wire Damaged

Pipe Section Details

Item	Traceability / Identification
Project Number	301229C002
Project Name	JULIMAR DEVELOPMENT PHASE 3
Pipe Section	SF301229C002.03
Structure number	ST203.72124
Affected Layer	Zeta Pressure Vault
Length Affected	768.2m
Drawing Number / MP Code / STA	ZETA 6.2 FI09 (MP205)

Overview of Anomaly

Problem Description:

During the zeta spiraling of JULIMAR DEVELOPMENT PHASE 3 SF301229C002.03 (ST203.72124), zeta wire damage was detected after accumulator at length 768.2m.

Root Cause:

The root cause was identified due to zeta wire offset/dislocated from roller accumulator and lead the wire damaged. The wire was dislocated due to gap for adjustment roller is too big (Original Design).

Immediate Action Taken:

Production performed un-spiralling, removed affected wires and re-weld before proceeding spiralling process. Dimension after repaired are all within criteria and accepted as per DP-QCP-08DAQT001.

Defect Photos



Figure 1 : Zeta wire damage was detected after accumulator at length 768.2m.

Repair Photos



Figure 2 : Production performed un-spiralling, removed affected wires and re-weld before proceeding spiralling process.

