



NCR No: 11961

QER: JULIMAR DEVELOPMENT PHASE 3 SF301229C002.05+06+07 - Zeta wires unlocked

Pipe Section Details

Item	Traceability / Identification
Project Number	301229C002
Project Name	JULIMAR DEVELOPMENT PHASE 3
Pipe Section	SF301229C002.05+06+07
Structure number	ST203.72124
Affected Layer	Zeta Pressure Vault
Length Affected	44.8m
Drawing Number / MP Code / STA	ZETA 6.2 FI09 (MP205)

Overview of Anomaly

Problem Description:

During the zeta spiraling of JULIMAR DEVELOPMENT PHASE 3 SF301229C002.05+06+07 (ST203.72124), zeta wire unlocked was detected at length 44.8m on the pipe.

Root Cause:

The root cause due to wires entangled in bobbin #002 during running causing wire damage and wire unlock at laying point.

Immediate Action Taken:

Reparation by un-spiral has been performed to re-position the wires to be in a good spiral. This reparation was accepted as it is and the dimension after the repair are within the criteria.

Defect Photos



Figure 1 : Zeta wire unlocked was detected at length 44.8m on the pipe.

Repair Photos



Figure 2 : Reparation by un-spiral has been performed to re-position the wires to be in a good spiral.

