

STEPPER COMMAND LIST

parameter [n] is optional motor number 1..
linefeed is \n

reset

power on default

gotoswitch [n]

goto limit switches

busy [n]

check whether the motor is rotating

wait [n]

wait until motor stopped

rotate [n] steps

rotation +/-steps (three sixty = ~~200~~⁴⁰⁰ * microsteps)

setprofile [n] microsteps acceleration speed

set microsteps=1,2,4,8,16,32,64 or 128 (default 8)

set acceleration steps/sec^2 (default 1000)

set speed steps/sec (default 500)

setvoltage [n] driving holding

set driving voltage (default 2.8) ^{6.8}

set holding voltage (default 1.0) ²

getvoltage

return actual supply voltage

setpos [n] step

drive to absolute position

getpos [n]

return absolute position

clearpos [n]

set counter to zero

run [n] speed

run endless +/-speed steps/sec

softstop [n]

stop rotation of motor with deceleration

hardstop [n]

stop rotation of motor immediately (counter errors occur)

hiz [n]

switch off stepper coils

adjust [n]

show values in range -50%...0...+50% until [return] pressed
trim poti on L6470 board with screw driver to zero