



Diagnóstico	
	Diagnóstico: PARAFUSOS DE FIXAÇÃO DAS DIAGONAIS DO EIXO 03, FILAS B E C SITUADOS ENTRE AS ELEVAÇÕES EL.9300 A 21250 COM CLASSE DE DEGRADAÇÃO CD03.COMPONENTE COM DEGRADAÇÃO QUE CAUSA REDUÇÃO MENSURÁVEL DA CAPACIDADE ESTRUTURAL. DESENHO: DF-325K-42-08030/07308; DF-3250KP-G-00000-M-51375 MATERIAIS: 144 PARAF.CAB. SEXT.Ø3/4"X2"-C/PORCA SEXT. E ARRUELA LISA A-325

Recomendação: SUBSTITUIR TODOS OS PARAFUSOS ENTRE AS ELEVAÇÕES CITADAS DO EIXO 03 E FILAS B E C, TROCAR SOMENTE OS FIXADORES DA CHAPA DE ESPERA DOS CONTRAVENTAMENTOS, NÃO SUBSTITUIR PARAFUSOS DAS TRAVESSAS(VIGAS)

The image is a composite of five panels. The top row contains two photographs: FOTO 1 (left) and FOTO 2 (right). The bottom row contains two panels: FOTO 3 (left) and a structural drawing (right).
 - FOTO 1: A close-up photograph of a concrete wall corner showing significant spalling and exposed aggregate.
 - FOTO 2: A photograph of a concrete wall surface with several large, irregular holes and areas of delamination.
 - FOTO 3: A photograph of a complex steel truss structure, likely part of a bridge or large industrial building, showing multiple intersecting beams.
 - ELEVACÃO DO EIXO '3': A technical structural drawing showing a cross-section of a structure. It includes vertical dimensions (e.g., 11000, 13000, 15000) and horizontal dimensions (e.g., 1000, 2000, 3000, 4000, 5000, 6000, 7000, 8000, 9000, 10000, 11000, 12000, 13000, 14000, 15000). The drawing shows a grid of vertical lines labeled E, D, C, B from left to right. It also shows horizontal lines with various elevation markers (e.g., EL.+21250, EL.+16750, EL.+13450, EL.+9300, EL.+9000) and structural details like reinforcement bars and concrete sections.