UptimeEquip
Innovative Maintenance Support Program

SelectEquip
Flexible Innovative Packaging Systems

GENERAL SERVICE REPORT

Customer:	Tassal DeCosti	**Date:**	21st January
Site Address:	29 Bachell ave Lidcombe	**Site Contact:**	Darryn.Hicks@tassal.com.au
		Phone:	0427 963 625
Customer PO		**Internal Job :**	5937

Subject: ***Called in due to trays crashing***

Equipment Type:	Serial Number:	Customer Line # (if applicable):
Trave 1000	00927	Skin line
Trave 1000	11377	High care MAP
Trave 1200	A16A-11326	Map
Trave 1000	12479	Tropica MAP

Equipment condition:

Work Performed:

Wednesday 21st

Line 1 Trave 1200
Tooling 9x5 slow recipe.

- *Arrived for start-up on Line 1 and line 3, and could only work on one line at a time so started line 1 Trave1200*
- *The infeed and spacer belt was replaced the night before for new type which did not work, the belt was too slippery and trays could not space out correctly.*
- *Removed the infeed and spacer belts to put back the white original belts.*
- *Started making some adjustments to the spacer belt tray gap for better clearance*
- *Made some adjustment to pusher arms for smoother transfer*
- *With all the above changes and saved the line ran well, but please note* ***61ppm*** *on 9x5 trays is constant and to run any faster you need to work on upstream on tray contamination.*

Tooling 9x7 Fast recipe

- *Made a few changes to the spacer belt tray gap for better clearance.*
- *Made a few changes to the pusher arm for smooth transfer*
- *Tool was sealing badly so removed the top head and cleaned sealbars free off contamination.*
- *Replaced one of the T/seal which was damaged and all the other will need replacing sometime.*
- *Replaced the out O'cord which was damaged for better vacuum.*
- *Watched production and ran well at* ***58ppm***.

Line 3 Trave 1000
Tooling 9x5 no phaser

- *This line was running badly and could only achieve 35ppm.*
- *The chain line had to be moved to one side and closer to the infeed belt, maximum of 2mm gap.*
- *Made a few changes to the spacer belt gap for better clearance*
- *Made some changes to the pusher arm for smoother transfer*
- *Made changes to the film wind for better aligning.*
- *Increased the line speed to* ***55ppm*** *with chain line running at 86 Hz*
- *Watched production and for 15min the line ran at* ***55ppm*** *without stopping zero alarms.*

Tooling 9x7

- *After moving the chain line on 9x5 tooling the 9x7 tool transfer from chian line run well.*
- *Made a few changes to the spacer belt for better tray gap*
- *Cleaned up the pusher arm cycle for smoother transfer*
- *The line was running at* ***54ppm*** *with no issue.*

UptimeEquip
Innovative Maintenance Support Program

SelectEquip
Flexible Innovative Packaging Systems

GENERAL SERVICE REPORT

SPARE PARTS USED				
Part Number:	**Description:**	**Qty:**	**Chargeable?**	
			Yes ☐	No☒
			Yes☐	No☒
			Yes☐	No☒

TECHNICIAN HOURS	**Marc Ashford**	
Time	**Start**	**Finish**
Travel To Site:	05:30	06:00
Onsite:	06:00	16:00
Travel From Site:	16:00	16:30
Remote assistance:		
Report writing:	15min	
Overnight stay	☐	
Overnight stay with flights	☐	

REPORT SIGN OFF			
	Print Name:	**Signature:**	**Date:**
Customer:		X _____	21st January
Technician:	Marc Ashford		

Select Equip
7 Gatwick Road Bayswater North
Victoria 3153 Australia
Phone +61 (3) 8720 8400

Trading as Select Equip
Select Packaging Systems Pty Ltd ABN 59 087 731 520
spares@selectequip.com.au www.selectequip.com.au