UptimeEquip
Innovative Maintenance Support Program

SelectEquip
Flexible Innovative Packaging Systems

GENERAL SERVICE REPORT

Customer:	Huon Aquaculture	**Date:**	15/06/2021
Site Address:	7218 Bass Highway, East Sassafras | TAS 7307	**Site Contact:**	Chris Newett
		Phone:	0418 994877
Customer PO #:		**Internal Job #:**	2634

Subject: problems with both Raw and Smoke lines

Equipment Type:	Serial Number:	Customer Line # (if applicable):
Trave 340	A/14/A-00911	Raw Line
Trave 340	A/14/A-00912	Smoke's room
Skin tool	132x224xH15mm	Smoke's room
MAP 9x5	224x132xH40	Raw line
MAP 11x9	C/16/A-04805	Raw line (290x226)
MAP 9x7	STS 2012	Raw line (170x222)

Equipment condition:

The Raw line Trave need to replace cam shafts and bearings, 9X7 tool need rebuilding as well

Work Performed:

Smoke's room line was inspected and found the main vacuum hose was damaged reason why they were getting bad sealing, after the hose was repaired the product presentation looked good. There is extra work for improvement but they need to run at the speed which makes it difficult to make any improvements.

The Raw Line Trave 340 needs a major service by replacing cam shaft and bearings, the film reel gearbox needs replacing as well and I believe all above parts have been ordered

The 9x7 tool needs a rebuild by replacing all internal springs and knife of which I believe have been order.
This tool did not perform well but once the tool has been rebuilt this should make a difference in presentation.

The problems found with Raw Line was main vacuum valve had build-up of waist film around the spout area which was causing the vacuum to leak during the cycle.

The compensating valve was loose and would have caused problems with atmosphere leakage which is now fixed.

Select Equip
7 Gatwick Road Bayswater North
Victoria 3153 Australia
Phone +61 (3) 8720 8400

Trading as Select Equip
Select Packaging Systems Pty Ltd ABN 59 087 731 520
spares@selectequip.com.au www.selectequip.com.au

UptimeEquip
Innovative Maintenance Support Program

SelectEquip
Flexible Innovative Packaging Systems

GENERAL SERVICE REPORT

SPARE PARTS USED				
Part Number:	**Description:**	**Qty:**	**Chargeable?**	
			Yes ☐	No☒
			Yes☐	No☒
			Yes☐	No☒

STATUS		
Machine Tested?	Yes☒	No☐
Comments:		
Revisit Required?	Yes☐	No☒
Comments:		

RECOMMENDATIONS
Comments: Would be good to come back and replace the cam shafts, bearings and retune the 9x7 tool after internal springs have been replaced

RECOMMENDED SPARE PARTS		
Part Number:	**Description:**	**Qty:**

TECHNICIAN HOURS					
	Date: 15/06/2021			**Date: 16/06/2021**	
Time	**Start**	**Finish**		**Start**	**Finish**
Travel To Site:	07:15	07:45		06:15	06:45
Onsite:	07:45	15:45		06:45	15:45
Travel From Site:	15:45	16:15		15:45	16:15

REPORT SIGN OFF			
	Print Name:	**Signature:**	**Date:**
Customer:		X _____	16/06/2021
Technician:	Marc Ashford		

Select Equip
7 Gatwick Road Bayswater North
Victoria 3153 Australia
Phone +61 (3) 8720 8400

Trading as Select Equip
Select Packaging Systems Pty Ltd ABN 59 087 731 520
spares@selectequip.com.au www.selectequip.com.au