UptimeEquip
Flexible Innovative Packaging Systems

SelectEquip
Flexible Innovative Packaging Systems

MONDINI TECHNICAL SERVICE ROUTINE

CUSTOMER:	Huon	**DATE:**	17/11/2021
ADDRESS:	Tasmania	**CONTACT:**	Tony
		MACHINE NO:	A/14/A-00911

Equipment type/s:	**Trave 350**	**Machine Cycles:3682961**	**Push Cyles:3685581**
Product description:			**Run Time:**
Was the machine running before the service?	**Yes ✓ No**		**Comments:**

Description	Comment	OK	Description	Comment	OK
Belts , Cords and Rollers			**Under Machine**		
Condition of Infeed belt		✓	Main motor brake adjustment 0.3 mm	Servomotor	✓
Condition of spacer belt		✓	Pusher motor brake adjustment	Servomotor	✓
Check Phasers and Guides	N/A	✗	All Sensors Tight and operational		✓
			All Rod ends Tight		✓
Condition of out feed cords	Worn but useable	✓	Check Air and gas system		✓
Check Bearings		✓	Main lifter gearbox fluid level		✓
Check Sensors / Reflectors		✓	Pusher Arm gearbox fluid level		✓
Inspection and adjustments of Timing Belts			Lubricate all Lube points		✓
Infeed		✓	Check filter vacuum Pump		✗
Spacer		✓	**Infeed Belt (Load Belt)**		
Outfeed		✓	Check all sprockets &Lubricate		✓
Track Belts		✓	Check conveyor Tension		✓
Film			Check Condition of Tray Guides		✓
Check position of spreader cones	Modified	✓	Check Operation of start/stop E-stop		✓
Check scrap rewind tension		✓	**Lifting Plate**		
Check condition of Airshafts		✓	Change O'Rings	Still good	✓
Check condition of film path rollers		✓	Check hoses of Gas & Vacuum	Vacuum test good	✓
Check tracking of rollers		✓	Check height of mobile plate		✓
Check air leaks		✓	Check upper slides for Nylon		✓
Film – Film Advance			Check solenoids		✓
Nylon gears		✓	Check doors and door locks		✓
Roller & Bearings		✓	**Electrical**		
Check nylon bushing on film break		✓	Inspect Electrical Cabinet for loose	See comments	✓
Rubber Roller		✓	Check discoloured (hot) connections		✓
Breaking sensor	Flaps Removed	✓	Check All switches		✓
Film – Reel Unwind			Check operation of machine Interface		✓
Airshalft for leaks		✓	Battery of PLC		✗
O-Cord Condition	N/A	✓	Battery of machine Interface		✗
Film Path			Infeed Timing and Setup		✓
Operation of dancers		✓	Check Phasers Alignment		✓
Pendulum		✓	**Reset all Alarms)**		✓
Sensors		✓	**Test Run Machine (with Product**		✓
Photocell for printed film	N/A	✓	**If applicable**		

Extra Value added:

The following has been done extra:

Wednesday 17/11/2021:

Arrived onsite and met with Tony who showed me around and discussed all issue they have with the machines.

1. After discussion I fixed the following recipes on the Map machine (A/14/A-00911):

    - T09-280g R1
    - T11-460g r1
    -

    Production was processing the whole day and they advised me that they will be finishing at 17h00. When production finished I did attempt to diagnose the faulty denester. Due to the complexity, one of the following scenarios exist as it is evident that the problem is on the positioning of the motor.

    1. Motor faulty due to faulty internal resolver.
    2. Faulty Cabling
    3. Faulty VSD.

    Due to the environment I suggest replacing the motor with the resolver cabling.

2. When inspecting the top panel, I noticed a wire dislocated from the PLC. I referenced the wire on the drawing and found that this wire is for the film break flaps. The flaps is also physically removed. I suggest re-installing these flaps.
3. I had an inspection on the machine as indicated on the sheet above.
4. Although I had an inspection on the skin machine while it was operating, less attention was given to it as it was functioning as required.

Thursday 18/11/2021:

Arrived onsite and made and reduced the gas pressure from 3.5 Bar to 2.8 Bar. Fine-tuned the recipes accordingly.
I inspected the diaphragm on the upper gas. I found a split in the diaphragm. I could not obtain a spare diaphragm. I swopped the upper gas valve diaphragm with the second lower gas valve. I advised Tony that this diaphragm should be replaced as soon as possible.
Followed production throughout the day and the machines performed very well.

Suggestions:

- Replace the diaphragms of the second gas valve and inspect these diaphragms on the gas valves more often.
- Replace the denester servo motor and cabling.
- Re-install the film break flaps.

RECOMMENDED SPARE PARTS		
Part Number:	**Description:**	**Qty:**
13850010-LCL	Diaphragms for the gas valves	10
See attached picture	Denester Servo Motor	1
410000000206	Denester servo motor cabling	1
410000000744	Denester VSD (8V1016.00-2)	1
410000000671	Resolver Card on the VSD (8AC122.60-3)	1

TECHNICIAN HOURS					
Time	**17/11/2021Start**	**17/11/2021Finish**		**18/11/2021Start**	**18/11/2021Finish**
Travel To Site:				06:00	07:00
Onsite:	10:00	17:00		08:15	16:00
Travel From Site:	17:00	17:15		16:00	16:15

REPORT SIGN OFF			
	Print Name:	**Signature:**	**Date:**
Customer:	Sam Hodder	X _____	18/11/2021
Technician:	Bertus Reynolds		