UptimeEquip
Flexible Innovative Packaging Systems

SelectEquip
Flexible Innovative Packaging Systems

GENERAL SERVICE REPORT

Customer:	Coles RROA	**Date:**	26/7/22
Site Address:		**Site Contact:**	Trent
		Phone:	
Customer PO #:		**Internal Job #:**	2693

Subject: setup recipe for new dome heights

Equipment Type:	Serial Number:	Customer Line # (if applicable):
Trave 590 DOT		

Equipment condition:

Normal

Work Performed:

26/7/22
Arrived onsite for support
New domes have been installed dome height is now 35mm
Film Cryovac VST0380T
Ran cycles and found film popping during foaming
Played with delay of 2nd valve for forming
Fine-tuned tool lift delay to suit forming cycle
Increased temp to help with forming.
The forming cycle is now good with no roll off or popping
Made new recipe call KB 11x7 35mm Dome and saved
Had good run on sizzle steak scotch fillet just had a few issue with porterhouse
Being that the product is shingled it leaves air gaps which make it impossible for the film to get down that cavity, once the meat temp increased we had much better ran with porterhouse.
Saved all setting to KB 11x7 35mm dome
Monitored normal production with this recipe ran with no issue
28/7/22
Arrived onsite to try and get better result with porterhouse
Sizzle steaks had a big run and had no issues
But when it came to the bigger steaks which are shingled and crusted the film would pop constantly there are two main factors for this
The steaks are right to the edge of the tray
Massive cavities between the steaks
Made new recipe without using top air as compensation this helped but it's hard to say as it was reworks and the temp of the meat had change making the cavities easier to seal.
Recipe is call 11x9 35mm dome no air

Select Equip
7 Gatwick Road Bayswater North
Victoria 3153 Australia
Phone +61 (3) 8720 8400

Trading as Select Equip
Select Packaging Systems Pty Ltd ABN 59 087 731 520
spares@selectequip.com.au www.selectequip.com.au

GENERAL SERVICE REPORT

Massive catvities

too close to edge

As the product temp changed the meat would cover the cavites and the tary would seal but when crusted temp product is stiff and asking too much streach of the film

Did have better seccsess when product softern up

SPARE PARTS USED

UptimeEquip
Flexible Innovative Packaging Systems

SelectEquip
Flexible Innovative Packaging Systems

GENERAL SERVICE REPORT

Part Number:	Description:	Qty:	Chargeable?	
			Yes ☐	No☐
			Yes☐	No☐
			Yes☐	No☐

STATUS		
Machine Tested?	Yes☐	No☐
Comments:		
Revisit Required?	Yes☐	No☐
Comments:		

RECOMMENDATIONS
Comments:

RECOMMENDED SPARE PARTS		
Part Number:	**Description:**	**Qty:**

TECHNICIAN HOURS	26/7/22		28/7/22	
Time	**Start**	**Finish**	**Start**	**Finish**
Travel To Site:	3:30	5:00	8:00	9:30
Onsite:	5:00	10:00	9:30	16:30
Travel From Site:	10:00	11:30	16:30	18:00

REPORT SIGN OFF			
	Print Name:	**Signature:**	**Date:**
Customer:	Trent	X _____	26/7/22 28/7/22
Technician:	Tim Harrison		

Select Equip
7 Gatwick Road Bayswater North
Victoria 3153 Australia
Phone +61 (3) 8720 8400

Trading as Select Equip
Select Packaging Systems Pty Ltd ABN 59 087 731 520
spares@selectequip.com.au www.selectequip.com.au