UptimeEquip
Flexible Innovative Packaging Systems

SelectEquip
Flexible Innovative Packaging Systems

GENERAL SERVICE REPORT

Customer:	Hilton foods Truganina	**Date:**	6th February
Site Address:	Victoria Melbourne	**Site Contact:**	George Karagounis
		Phone:	048702 2551
Customer PO #:		**Internal Job #:**	5984

Subject: Foil tray trials and TH300 film trials

Equipment Type:	Serial Number:	Customer Line # (if applicable):

Equipment condition:

Work Performed:

Friday 6th

Line 14

Trave 590 machine A14A-00893
Aluminium foil tray trials VIC5030 on Recipe T24 9X7 FOIL TRAY 58mm

- recipe had to be adjusted on the following
- slow down spacer belts for better control from 73hz to 55hz.
- adjust spacing on foil trays on spacer belt for better gap.
- adjust pusher arms for smooth transfer
- Tool needed to be aligned due to tray trimming.
- Once the alignment was done no trimming was detected.
- tool temp 210C
- film width 440mm
- the double conveyor phaser system damages the bottom of the trays due to weight, this can be rectified by only running one side of the conveyor and to leave a gap between trays.

GENERAL SERVICE REPORT

Line 2

- Main vacuum valve was playing up, lubricated the air-lines and replaced faulty control valve.

Line 5

- problems with inlet phaser system on chain line transfer
- replaced sensor and air-flow valves, with no result
- found that the main control valve was sticky.
- removed the main valve to lubricate and reinstall.
- test and ran production which seem to run okay.

Line 1 Trave 590 machine A22A-12940
Skin tool VIC5008 medium DOT trials on TH300

-we had some problems with cutting the film with following problems found and fixed,

1. *Air leak in the cabinet caused by lose fitting, this was retightened.*
2. *Lower shuttle plate temperature was set too high at 60 Degrees and had to reduce to 43 Degrees.*
3. *Once we got the above to cut film we had problems with film forming in to the dome*
4. *We tried to run on single step and double step with no success.*
5. *The film started get worse as we ran in such a way that no forming was possible.*
6. *We were not able to continue running and had to cancel the trial.*

NOTE: flights was delayed and cancelled due to bad weather

SPARE PARTS USED				
Part Number:	**Description:**	**Qty:**	**Chargeable?**	
			Yes ☐	No☐
			Yes☐	No☐
			Yes☐	No☐

STATUS		
Machine Tested?	Yes☐	No☐
Comments:		
Revisit Required?	Yes☐	No☐
Comments:		

Select Equip
7 Gatwick Road Bayswater North
Victoria 3153 Australia
Phone +61 (3) 8720 8400

Trading as Select Equip
Select Packaging Systems Pty Ltd ABN 59 087 731 520
spares@selectequip.com.au www.selectequip.com.au

UptimeEquip
Flexible Innovative Packaging Systems

SelectEquip
Flexible Innovative Packaging Systems

GENERAL SERVICE REPORT

RECOMMENDATIONS
Comments:

RECOMMENDED SPARE PARTS		
Part Number:	**Description:**	**Qty:**

TECHNICIAN HOURS	Marc Ashford	
Time	**Start**	**Finish**
Travel To Site:	05:30	06:00
Onsite:	06:00	15:30
Travel From Site:	15:30	21:00
Remote assistance:		
Report writing:	15min	
Overnight stay	☐	
Overnight stay with flights	☐	

REPORT SIGN OFF			
	Print Name:	**Signature:**	**Date:**
Customer:		X _____	
Technician:	Marc Ashford		

Select Equip
7 Gatwick Road Bayswater North
Victoria 3153 Australia
Phone +61 (3) 8720 8400

Trading as Select Equip
Select Packaging Systems Pty Ltd ABN 59 087 731 520
spares@selectequip.com.au www.selectequip.com.au