UptimeEquip
Flexible Innovative Packaging Systems

SelectEquip
Flexible Innovative Packaging Systems

GENERAL SERVICE REPORT

Customer:	Baiada Beresfield	**Date:**	7th February
Site Address:	Beresfield	**Site Contact:**	Mark Rooke
		Phone:	0401 704 186
Customer PO #:		**Internal Job #:**	5991

Subject: Pusher arms bushings

Equipment Type:	Serial Number:	Customer Line # (if applicable):
Trave 590	A/21/A-12636	Value added L1
Trave 1000	A/15/A-11189	Value added L2
Trave 1000	A23A-13202	Value added Room 2
E390	2857	Traypack L1
Trave 1000	A/16/A-11301	Traypack L2
Trave 1000	A/17/A-11735	Traypack L3
Trave 590	A12A-00516	Value added L3

Equipment condition:

Printed film

Work Performed:

Saturday 7th

- *Called out due to problems with Line 3 and line 1 in Traypack*

Line 3

- *They were having problems with reworks and bad sealing and to overcome they sealed at 2 seconds.*
- *Removed the top tool from machine and top counter tool.*
- *The sealbars were badly contaminated and had to be cleaned free off any contamination*
- *Looking as the sealbars they need to be send away for recoating*
- *The insulation foam needs to be replaced as well.*
- *Found the vacuum was leaking on the non-operator side due to wrong hose size, this has been rectified but will need to order the correct hose size.*
- *Once the sealbars were cleaned the tool was tested and recipe saved at 1.2sec sealing time which help and they ran without any sealing problems.*

Line 1

- *Need me to get the inlet phaser to work so they can run at 58ppm and it's now they are running at 51ppm.*
- *Removed the valve bank and replaced the inlet phaser pilot valve and lubricated the cylinders, please note this is due to water in the compressed air.*
- *After making the change and lubricated the cylinders it seem to run well at 58ppm, but this only lasted for 30min before the inlet phaser started playing up again by doing a double pulse.*
- *Removed the exhaust and exit phaser pilot valves to be replaced.*
- *Once the pilot valves were replaced they ran well at 58ppm and we could see a big difference in the movement of the cylinders.*
- *Watched production for a while and they ran good.*

Select Equip
7 Gatwick Road Bayswater North
Victoria 3153 Australia
Phone +61 (3) 8720 8400

Trading as Select Equip
Select Packaging Systems Pty Ltd ABN 59 087 731 520
spares@selectequip.com.au www.selectequip.com.au

GENERAL SERVICE REPORT

TECHNICIAN HOURS	Marc Ashford	
Time	**Start**	**Finish**
Travel To Site:	05:00	07:00
Onsite:	07:00	13:30
Travel From Site:	13:30	15:30
Remote assistance:		
Report writing:	15min	
Overnight stay	☐	
Overnight stay with flights	☐	

REPORT SIGN OFF			
	Print Name:	**Signature:**	**Date:**
Customer:		X _____	7th February
Technician:	Marc Ashford		

Select Equip
7 Gatwick Road Bayswater North
Victoria 3153 Australia
Phone +61 (3) 8720 8400

Trading as Select Equip
Select Packaging Systems Pty Ltd ABN 59 087 731 520
spares@selectequip.com.au www.selectequip.com.au