UptimeEquip
Innovative Maintenance Support Program

SelectEquip
Flexible Innovative Packaging Systems

GENERAL SERVICE REPORT

Customer:	Baiada Beresfield	**Date:**	22 September 2025
Site Address:		**Site Contact:**	Dale Hunt
		Phone:	0428100594
Customer PO #:		**Internal Job #:**	5725
Subject: Uptime			

Equipment Type:	Serial Number:	Customer Line # (if applicable):
TRAVE 590	A/21/A-12636	Line 1 Value added
TRAVE 1000	A/15/A-11189	Line 2
E390	2857	Line 4
TRAVE 590	A/12/A-00516	Line 3 Value added
TRAVE 1000	A23A-13202	Line 1 Tray pack
TRAVE 1000	A/16/A-11301	Line 2 Tray pack
TRAVE 1000	A/17/A-11735	Line 3 Tray pack

Equipment condition:

22 September 2025

I was not informed about the FOIL tool test; I left site at 11:00 after the morning startup.
On my way home I was informed that I had to go back and do the test.
Arrived on site at 14:00

The tool was inserted into the machine by Baiada Staff; I noticed that the bottom tool element was not heating up.

At this point the staff were not ready to do trails as they were looking for trays, product and film.

This gave me time to investigate

- *Reloaded another recipe Foil tool with a sealing time of 2 seconds*
- *Opened the water*
- *Enabled the enables for the bottom water flow*
- *Enabled the bottom tool temp*
- *Reset the alarms, water started flowing and then stopped*
- *No water was flowing from the machine*
- *Did fault finding, removed the float from the machine and inspected no water were flowing towards the Float*
- *The needle was also stuck because of corrosion*

GENERAL SERVICE REPORT

- *Got it unstuck by turning it upside down*
- *Inspected the solenoid valves*
- *Removed valves and opened to inspect.*
- *Found water on the other side*
- *Valves were blocked with corrosion, and the solenoid did not want to operate*
- *Checked the 24-volt DC supply*
- *Rebooted the machine*
- *Reloaded the FOIL tool 2.0 recipe and followed the same procedure to make sure all the enables were enabled.*
- *I could not get the water to flow out of the machine as I ran out of time.*
- *Spoke to Marc Ashford and it was decided that me or another tech would return the next day.*

I packed up and left side at 17:00 as I have been onsite from 06:00 for the startup and had to travel back to Sydney.

SPARE PARTS USED				
Part Number:	**Description:**	**Qty:**	**Chargeable?**	
			Yes ☐	No☐
			Yes☐	No☐
			Yes☐	No☐

STATUS		
Machine Tested?	Yes☒	No☐
Comments: Good		
Revisit Required?	Yes☐	No☐
Comments:		

RECOMMENDATIONS
Comments:

RECOMMENDED SPARE PARTS		
Part Number:	**Description:**	**Qty:**

UptimeEquip
Innovative Maintenance Support Program

SelectEquip
Flexible Innovative Packaging Systems

GENERAL SERVICE REPORT

TECHNICIAN HOURS	Henry Nieuwenhuis	
Time	**Start**	**Finish**
Travel To Site:		
Onsite:	14:00	17:00
Travel From Site:	17:00	19:30
Remote assistance:		
Report writing:	30 min	
Overnight stay	☐	
Overnight stay with flights	☐	

REPORT SIGN OFF			
	Print Name:	**Signature:**	**Date:**
Customer:		X_____	25/09/2025
Technician:	Henry Nieuwenhuis		